Certificate of Location of Government Corner

ID#: 731005 **Description:** SEC COR 9 10 15 16 73 **Date Set:** 11/4/2005 **County:** Olmsted

Section: 10 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with N-S fence and in line with fence east
County Survey Disk in S side 26" Oak W 37.53'
County Survey Disk in E side CP N 2.43'
Post w/sign 2' west
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes - Yerby, 80.00 chains and set post. Bearing trees 8" Burr Oak N65° W 53 links. 20" Burr Oak N70° E 58 links. 9" Burr Oak S52° E47 links. 22" Burr Oak S45° W 40 links.

5-1876 T. Hunter, (See T.H.Book 4, P. 122) Unrecorded survey.

5-1872 T. Hunter P. 201, No. 210 found corner, tested by Bearing trees. 16 N set stake M&L 19.94. Measure east from above 1/16 corner 39.70.

11-1964 J. Kerr, B.89 P.77. Set CIM in bedrock in cattle trail.

11-1969 J. Kerr found CIM (top above ground surface).

9-1996 County Surveyor found CIM in good condition.

11-4-2005 County Surveyor found CIM in good condition down 1.2' with corner post right next to monument, took local ties and removed. Also removed corner post, reset corner post 2.0' north of fence east and inline with fence north and south. Set 5' telspar w/CIC up 0.3' from local ties taken from CIM. CSD w/60d nail in south side of 26" Oak west 37.53' and CSD with concrete nail in east side of corner post north 2.43'. Set sign and post 2.0' west.