Certificate of Location of Government Corner

ID#: 731206 **Description:** 1/4 SEC COR 11 12 73 **Date Set:** 9/27/2006 **County:** Olmsted

Section: 12 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 5' east of centerline of N-S twp road and in line with fence west
PK nail in S side PP #19598 NNE 31.94'
County Survey Disk in N side gate post W 36.88'
County Survey Disk in SW side 30" Oak up 3 1/2' SE 77.84'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.00 set section post. 24 " burr oak N78W56 links, 10" burr oak N50E 57 links.

7-1902 W. Fraser P.22B corner gone, found NE Bearing Tree & stump of NW Bearing Tree. Reset corner with stake & stone 3"x8"x14" 16W found stone as 1/16 corner.

11-25-1969 J. Kerr found stones at center 11 and both 1/16 corner on E-W line.

11-28-1969 J. Kerr set CIM over 3/4"x12" steel re-bar & glass. Found measure center to center 1/16 stone.

9-20-2006 County Surveyor found CIM down 1.6' in good condition, found 5/8"x6" iron rod lying flat in hole. Also found nail in hole lying flat, removed both. Corner post to the west replace, pk nail and tree ok.

9-27-2006 County Surveyor found CIM down 1.6' in good condition, took local ties and removed. Found 3/4" rod down 3.2' in good condition, ties matched to CIM. Set 5 1/2' telspar pipe w/CIC down 0.45' over rod. CSD w/concrete nail in north side of gate post west 36.88'. CSD w/60d nail in SW side of 30" Oak up 3 1/2' SE 77.84' and pk nail in south side of PP #1959 near ground NNE 31.94'.