Certificate of Location of Government Corner

ID#: 731304 **Description:** 1/4 SEC COR 13 24 73 **Date Set:** 12/7/1989 **County:** Olmsted

Section: 13 **Township:** 107N **Range:** 13W **Monument Description:** 5/8" brass plug

Reference Ties:

The corner falls in centerline of CSAH 2
Ref. pipe NW 168.69'
County highway disk in top center CP SSE 62.13'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.00 Set temp sec post west on true line between 13 & 24 course 9° 16' E. 40.00 1/2 set section post. 7" burr oak N80 W34 links, 7" burr oak S72 W 25 links.

7-1874 T. Hunter, P.258, No.258 - Corner gone, found NW Bearing Tree stump. Reset 1/4 post from Bearing tree stumps. Measure east to stone set Bearing tree 39.82'.

1891 T. Fraser Bk.8, P.2, Section 13, Found iron stake as corner set by Hunter.

8-31-1976 County Surveyor found stake hole with wood pieces.

9-1-1976 County Surveyor set 3/4" x 2' rod at stake hole location.

8-8-1986 County Surveyor set transit tie 3/4" pipe w/cap 91/2' south of corn crib.

12-7-1989 county highway department 5/8" brass plug in centerline CR 2. county highway department disc in top center corner post SSE 62.13'.

9-21-2006 County Surveyor found brass plug with punchmark down 0.1' in centerline of CSAH 2. Corner post is now leaning SE and is bad. Ref monument is 5/8" pipe w/cap RLS 8952.