Certificate of Location of Government Corner

ID#: 731605 **Description:** SEC COR 16 17 20 21 73 **Date Set:** 11/15/1963 **County:** Olmsted

Section: 16 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in line with fence south and 2' north of E-W fence
Sign on CP 2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 80.00 set section corner post, made trench. 15" Burr Oak S5° E121 links.

4-1858 T. Hunter P.54, No.78 - Used corner. Set 1/16 east M&L 19.75 (1303.5).

6-1877 T. Hunter Field Bk. 4 P. 176-177 unrecorded survey. Something used as section corner shows bearing trees & measure east 19.75 - 1975 to 1/4 cor. 16-21.

5-1894 W. Fraser, P.549, No.507 Mr. Robinson avers corner stood in E-W fence. Measure S1/4 17 to S1/4 16 & set stone as corner. Measure east 39.853/4 (2630.60). Measure W 39.923/4 (2635.2), 16N set stake M&L 19.871/2 (1311.75).

6-1896 T. Hunter P.602 No.547 found stone. 16 east set stone 2"x10"x24" M&L 19.93 (1315.38).

11-15-1963 J. Kerr, Set CIM over 1" steel rod. Measure south 2626.8 to rod set M&L.

11-20-1972 County Surveyor found 1/16 stone east, offset 100' south at 1/16 section corner. Measure between 1314.0, cont line & measure east. Couldn't find 1/4 16-21. Set stone & iron there.

11-14-1989 County Surveyor found CIM in good condition. Nailed survey marker sign to corner post.

10-19-2005 County Surveyor found CIM at surface in good condition.