Certificate of Location of Government Corner

ID#: 731606 **Description:** 1/4 SEC COR 16 17 73 **Date Set:** 5/2/1974 **County:** Olmsted

Section: 16 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' south of centerline of E-W twp road and 4' east of fence north
Nail in E side RR Tie CP N 23.74'
County Survey Disk in PP #Q6077 SW 50.84'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 40.00 set section post. 9" Burr Oak W70° W49 links.
10" Burr Oak S 58° E75 links.

5-1894 W. Fraser P.549, No.507. couldn't find corner. Set stake & stone M&L 39.75 (2623.5'). 16N set stake M&L 19.871/2 (1311.75). 16S set stake M&L 19.871/2 (1311.75).

9-1901 W. Fraser, P.549, Set 1/16 stone & stake M&L W 20.031/2 (1322.31). Set 1/16 stone & stake M&L W of SE17 19.97 (1318.0).

?? Corner seems to be gone. McGhie set rod as assumed corner.

8-17-1966 J. Kerr, Found McGhie rod.

5-1969 J. Kerr B.98 P.58, Set CIM (wrong) over 1"x18" iron. 1/16 fence N running W from NE17 1311±. 1/16 fence S running E from SE 17 1314.35±. Nail in pp SW 48.08. Nail in R.R. Tie corner post 3' W of N 23.74.

8-1969 John Kerr, County Surveyor, found a rod set in area of corner. Dug around rod but found nothing. Measured East line Sec. 17 and set a C.I.M. midway and on line.

1971 County Surveyor Note: believe McGhie rod near exact M&L, believe CIM set there.

5-1-1974 County Surveyor reset CIM. Reset 1"x2" rod.

5-2-1974 County Surveyor dug in area of C.I.M. and found true stone and stake with a boulder on top of all. Reset a 1"x24" rod between the stake and stone and set a C.I.M. over all. Correct corner is 1.0' north and .4' east of John Kerr's monument.

9-22-1989 County Surveyor found CIM pp #34317 gone. Checked tie to R.R. tie corner post and to CSD in pp#Q6077 SW 50.84'.

10-19-2005 County Surveyor found CIM down 1.1' in good condition.