Certificate of Location of Government Corner

ID#: 731706 **Description:** 1/4 SEC COR 17 18 73 **Date Set:** 11/7/2011 **County:** Olmsted

Section: 17 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe with cap RLS 42638

Reference Ties:

The monument is at the surface
The corner falls in centerline of E-W twp road and 11' east of driveway south
County highway disk in W side CP SSE 34.10'
County Survey Disk in PP #Q6060 NE 46.59'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.00 set section post in mound, made trench, planted Osage Orange seeds E&W of trench.

4-1864 Compton Pg. 80 No. 120 - Used 1/4 corner to set 1/16 west.

8-1871 R. Perry, P.187, No.198 couldn't find stake. Dodge avers he set his road fence n on line & 2 rods from corner.

8-1893 W. Fraser P. 526 No. 497 no evidence of corner. Set stone 21/2"x9"x24" M&L 39.87 (2631.42).
16S set oak stake M&L 19.931/2 (1315.71). 16W set stone 6"x6"x26" M&L 20.05 (1323.3).

5-1894 W. Fraser, P.549, No.507 measure north & south 39.87 (2631.42).

5-1966 J. Kerr run & measure section line N-S 5250.2 R5262.8. Set corner on line at record from s2631.4.

5-15-1969 J. Kerr set CIM by line and measure.

5-1-1974 County Surveyor found Fraser's stone. Removed Kerr CIM and set CIM over Fraser stone.

9-22-1989 County Surveyor found CIM, couldn't find punch cross in culvert. 34.10' to County Highway Department disc in corner post.

12-22-2003 County Surveyor found CIM down 1.2' in good condition.

11-6-2006 County Surveyor found CIM down 1.5' in good condition. Set reference pt "P132 E" and used MnDOT pt "P132 D" as reference pt. Referenced CIM and set survey marker nail at surface from ties taken from CIM.

11-7-2011 County survey crew found survey marker nail. Set 1" x 16" sq. pipe with cap over the survey marker nail. The CIM is assumed to still be inplace down 1.5' in bituminous road.