Certificate of Location of Government Corner

ID#: 731709 **Description:** SEC CEN 17 73 **Date Set:** 11/7/2011 **County:** Olmsted

Section: 17 **Township:** 107N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe with cap RLS 42638

Reference Ties:

The monument is at the surface
The corner falls in centerline of E-W twp road and in line with fences north and south
County Survey Disk in post SW 36.08'
County highway disk in old PP (now post) N 32.39'
Punch hole in top center 18" CMP NW 37.10'
This corner is located by GPS measurement

Corner History:

5-25-1894 W. Fraser, P. 549, No. 507 set stone. 16N set stake M&L 19.90. 16S set stake M&L 19.913/4.

5-1969 J. Kerr set CIM over 12" piece of 1" iron. Measure east 2644±, measure west 2634±. Disc in pp SW 36.0'. Disc in fence post 1' east of south 32.6'. Disc in pp North 31.5'. See pencil caption W. Fraser 1901 - see 1/4 16-17 stone E M&L 20.031/2.

5-2-1974 County Surveyor found stone. Reset CIM over electric fence post. 1/16 corner e center 17 found stone & set 3/4"x22" rod as corner.

8-1-1985 Yaggy Associates found and used monument at center of section 17.

9-22-1989 County Surveyor found CIM - checked ties - punch hole top center 18" culvert 37.10' NW. County Highway Department disc in pp (now fence post) 32.39' N C.S.D. in post 36.08' SW.

7-19-1990 V. Fangman found and used CIM at center of section 17.

9-18-1992 V. Fangman found and used CIM.

6-15-2001 Brand & Massey Surveying found and used monument.

10-10-2003 Massey Land Surveying found and used monument.

2-18-2004 R. Brand & Associates found and used monument.

10-19-2005 County Surveyor found CIM down 0.9' in good condition.

3-3-2006 McGhie & Betts found and used CIM.

11-6-2006 County Surveyor found CIM down 0.9' in good condition, took local ties and removed. Found rod down 2.5' in good condition, ties matched. Set survey marker nail in new blacktop from ties taken from CIM. Set reference pt "leaning cowboy" and Pk nail in PP and referenced survey marker nail.

11-7-2011 County survey crew set 1" x 2' sq. pipe with cap from coordinates measured in 2006. The survey marker nail is gone but the nail hole matches the 1" pipe.