Certificate of Location of Government Corner

ID#: 731806 **Description:** W 1/4 SEC COR 18 73 **Date Set:** 8/7/2003 **County:** Olmsted

Section: 18 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 7' south of centerline of CR 124
PK nail in NE side PP Q6044 (up 2') NW 58.27'
5/8" Iron S 80.51'
NE corner house foundation SE 176.25'
Ref pipe SE 74.17'
Ref pipe NNE 64.06'
This corner is located by GPS measurement

Corner History:

Gov't Notes: 40.0 set quarter section post. RPs- burr oak N48° W226 links, 5" burr oak N14° E175 links.

1871 R. Perry by T. Hunter P. 187 No. 198 all Bearing trees gone and grubbed. By digging found hole where old stake should have been. Set new stake - 16 north set stake M&L 20.08.

2-1878 T. Hunter P. 330 No. 324 found stake with iron rod driven by its side.

Caption 11 - 1888 T. Hunter found stake with iron rod driven by its side.

6-1964 J. Kerr found 3/4"x4' long pipe, set CIM over 1"x12" pipe at pipe found location.

4-1978 County Surveyor note: Revised survey data from M.H.D. filed in "Blue Book" at center 13. Survey has coord. on all corners (except SE) in section 13 plus Center 18.

8-11-1980 County Surveyor removed C.I.M. and found a 3/4"x11" rod beneath Left iron in place. The old road Was on sand subsoil 1.7 deep. The C.I.M. was 3' east of fence south. Dug from the CIM 3' North, 4' South, 41/2' East and 7' West. Found nothing. We were digging to cover Hunter full measure from NW 18 and Hunter measure from the Center 18 (which came 1' west of CIM). Found someone had dug about 3x3 here centered 41/2' West and 6' north of C.I.M.

8-12-1980 County Surveyor took additional references: CSD in large pp NW 58.51'. NE corner of house foundation just below siding SE 176.25'. 5/8" rod under fence south and + 13' west of a 9" poplar tree south 80.51'

9-1983 County Surveyor, 1 square pipe reset after road construction. Also set a 1" square x 30" pipe 74.17'. SE of corner and on line to NE corner of block foundation of house.

7-30-1984 County Surveyor set a 10" C.I.M. over 1" sq. pipe set in 1983

12-16-1997 McGhie & Betts found C.I.M. 7' south of center line of CR 124 and checked references.

4-29-2003 County Surveyor found CIM at surface in good condition. Set 1" square pipe w/cap as reference pipe for 2003 overlays. Tied out corner.

5-16-2003 County Surveyor removed 10" CIM for 2003 overlays. 1" square pipe w/cap down 1.2' was left in place.

8-7-2003 County Surveyor set 1" square pipe w/cap from overlay tie out information at surface of CR 124.

1-16-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.