Certificate of Location of Government Corner

ID#: 731904 **Description:** 1/4 SEC COR 19 30 73 **Date Set:** 7/6/1989 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in median, 41 1/2' east of centerline of SBL of CSAH 22 and 137' north of centerline of 26th St NE
Post w/sign 2' west
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 40.00 set temp section post east on true line between section 19&30 W89° 44'E 38.98 set section post. 10" Burr Oak N70 E74 links. 10" Burr Oak S25 E178 links.

4-1872 T. Hunter P.196, No.206 found stake. Measure east 40.30 (2659.5) S88° 55' E. Measure N. 39.66 (2617.56) N3/4°E.

9-1891 T. Fraser P.456, No.440 Used fence corner of fence south - original corner once F cor.

5-1894 W. Fraser, caption above, found stake in survey for road 7-13-1894, left as found.

12-3-1900 W. Fraser P.700, No.616 found stake, drive new stake in its place. Measure no 39.70 (2620.2') Measure west 18.0 then 7.50 then 12.68 (38.18) (1188.0') (495.0') (836.88) (2519.88)

3-1900 William Fraser (P. 661 No. 588) found Sec. Cor. 19-20-29-30 and measured 39.91 1/2 chs. North to 1/4 Cor. 19-20.

1-31-1973 County Surveyor found above survey in field Bk. 9 P.83-88 in detail.

3-1-1977 County Surveyor searched for Will Fraser's property corners set between 1/4 Cor. 19-30 and the W. Sec. Cor. 19-30. Could not find any of them.

3-22-1977 County Surveyor set CIM over RR spike, w section corner 19-30 (Sur. No. 616). Spike & CSD w. side of 5" Twin Boxelder 3' east of N-S fence SW 43.32'.

7-6-1989 County Surveyor found monument missing from road construction in 1987. Set cast iron cap on telspar pipe in median of CR 22. Set sign & post 1.0'N.

7-2-2003 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition. Set post w/sign 2.0' West.