Certificate of Location of Government Corner

ID#: 731905 **Description:** W SEC COR 19 30 73 **Date Set:** 10/14/1986 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner is most accessible from Rocky Creek Dr NE
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, 80.00 set corner post to 19-24-25-30. 14" Burr Oak N33/4° W716 links. 10" Burr Oak S11/2° W130 links. 14" Burr Oak S4° E120 links. 12" Burr Oak N31/2° E 710 links.

9-1858 T. Hunter Pg.56, No.82, Used corner in survey of N1/2 Sec. 24. Measure S 39.72 chains to 1/4 post.

10-1874 T. Hunter, P.300, No.295 Found stake, found stump of SW Bearing Tree & NE & NW Bearing Tree stumps. Reset corner from SW Bearing Tree. Measure west 39.66' (2617.56).

8-1876 T. Hunter, P.303 No.298 Found stake set P.300 (no measure).

12-1900 W. Fraser, P.700, No.616 Couldn't find corner measure W1/4 30 to W1/4 19 set midway 39.73'. 16W reset corner with stone and stake. Measure east 12.68' then 7.50', then 18 to N1/4 30. Drove gas pipe and set stone.

?? J. Kerr reset corner w 5/8"x6' rod packed in stones. Couldn't find pipe.

2-18-1977 County Surveyor found stone.

3-1-1977 County Surveyor accept as corner where stone found. Set CIC/24" p2. (pipe & cap gone 11-24-78).

10-14-1986 County Surveyor found 3/4" rerod, Reset from 3-1-77. Set cast iron cap over telspar pipe over re-rod found.

7-2-2003 County Surveyor found cast iron cap on telspar pipe in good condition.

12-19-2003 County Surveyor found cast iron cap on telspar pipe up 0.5' in good condition. Able to reach corner off of Rocky Creek Dr. NE.