Certificate of Location of Government Corner

ID#: 731906 **Description:** W 1/4 SEC COR 19 73 **Date Set:** 8/10/2012 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is up 0.4'
The corner falls 1' NE of corner post for fences north and west
Sign on CP SW
This corner is located by GPS reference stations "Stonehedge A & B"

Corner History:

10-1853 Gov't Notes, John Ball, 40.00 set 1/4 section post. 14" Burr Oak S1° E 358 links.
14" Burr Oak N36° W160 links.

4-30-1872 T. Hunter (Book A, P.196, No.206) found stake, tested bearing trees.

8-17-1876 T. Hunter (Book A, P.303 No.298) found original stake, tested NW Bearing Tree, No measure.

1-23-1878 T. Hunter (Book A, P.328, No.322) found stake, no measure.

3-22-1880 T. Hunter. T.H. Field Book 5, P.108 Sec. 24. No measure, wrong stone at center 24. Corner post accepted as corner. Iron pipe by post declared as corner. Dr. Wellner tore it out, set new master type corner post.

12-8-1900 W. Fraser, field book #9, Pg.83-88, Found stake & B.T.. Set new stake and stone 17x15x3. Meas. South.

9-1959 J. Kerr B.79, P.60 - Run line west to center, 2611.44 set 1/2" rod, 1/64 at 652.86 (1368P73) & 1/16 with 3/4" pipe at 1305.72 (B68 P73) survey run line N2627.34. Found stone w/cross. Set 1/2" steel M&L 1313.67. Run line north from 1/16 west. Totan N 2628.9, set rod at 1314.45.

3-6-1974 County Surveyor found 3/4" pipe on east side of Kreosote corner post.

4-10-1981 County Surveyor found pipe also at 1/64 W found 1/2" iron under E-W fence on the south side of the driveway.

7-2-2003 County Surveyor found 3/4" pipe up 0.4' in good condition.

12-19-2003 County Surveyor found 3/4" pipe in good condition.

9-11-2007 County survey crew found 3/4" pipe up 0.4' in good condition.

8-10-2012 County survey crew found 3/4" pipe in good condition. Removed and replaced with a 4' telspar pipe with cast iron cap.