Certificate of Location of Government Corner

ID#: 732006 **Description:** 1/4 SEC COR 19 20 73 **Date Set:** 4/6/1989 **County:** Olmsted

Section: 20 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' east of N-S fence, 42 1/2' north of the base of dam and 15' east of centerline of creek
Punch mark in 7th Rib back from end of 24" CMP WSW 34'
NW corner of conc cattle tank slab NE ± 42'
Post w/sign 1' west
This corner is located by GPS reference stations "Hostetter A & B"

Corner History:

1853 Gov't Notes,Yerby, 40.00 set section post in mound, made trench, planted osage orange seed E&W of trench.

6-1870 R. Perry P.180, No.191 found corner. 16S set stake M&L 19.95. 16E set stake M&L 19.871/2 (1311.75) to center set.

4-1872 T. Hunter P.196, No.206 found corner in mound. Measure south 39.90. Measure west to center 19 40.65, set inter lines.

1-1878 T. Hunter, P.328, No.322 measure N 39.791/2 South 39.911/2.

5-1878 T. Hunter P.342, No.336 found original 1/4 post. 16 e found corner set P.180 M&L 19.871/2 (1311.75).
16 n set point M&L 19.89.

3-1900 W. Fraser, P.661 No.588 found corner as recorded, P.342. Measure south 39.911/2. Measure north 39.791/2.

6-1958 J. Kerr, B73 P32, set rod by terminal corner post as corner.

4-5-1989 County Surveyor Note: No sign of J. Kerr iron or post.

4-6-1989 County Surveyor, set Cast Iron Cap on telspar pipe sign & post west 1'. Corner is 1.5' east of N-S fence & 42.5' north of the base of the dam.

5-30-1990 County Surveyor found cast iron cap on telspar pipe in good condition.

8-21-1992 County Surveyor reset Cast Iron Cap on telspar pipe after finding computation error. Set at prorated distance and kink in line of 9.56' east by W. Fraser note.

7-2-2003 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.

12-26-2003 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.