# Certificate of Location of Government Corner

**ID#:** 732009 **Description:** SEC CEN 20 73 **Date Set:** 11/4/2005 **County:** Olmsted

**Section:** 20 **Township:** 107N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 2 1/2' east of centerline of N-S twp road, 2' south of fence east and 79' north of centerline of twp road NW
Spike in 18" Oak ENE 49.92'
Spike in PP NW 88.15'
County Survey Disk in S side PP #39546 E 28.11'
This corner is located by GPS measurement

**Corner History:**

4-15-1858 T. Hunter P.55, No.79 set corner, measure east 20.0, N39.45.

6-10-1870 T. Hunter - R. Perry P.180, No.191 found corner. 16W set stake M&L 19.871/2 (1311.75).
16C SW1/4 20 set stake M&L 19.94 on N-S 1/16 line.

5-6-1878 T. Hunter P.342 No.336 found 1/16 corner west M&L 19.871/2.

3-22-1900 W. Fraser, P.661 No.588 set small stake at inter lines. 16N drove iron stake M&L 19.87 (1311.42).

6-24-1958 J. Kerr, B.73 P.32 Set center rod at 2608.

10-25-1963 J. Kerr set CIM over iron.

12-2-1963 K. McGhie found and used monument.

5-30-1990 County Surveyor found CIM 10" deep with spike & concrete nail above.

4-3-1992 R. Brand & Associates found and used CIM.

9-28-1992 V. Fangman found and used CIM at center of section 20.

11-18-1996 V. Fangman found and used CIM.

10-16-1997 V. Fangman found and used CIM.

11-23-1998 V. Fangman found and used CIM.

10-23-2000 GGG found and used CIM.

5-26-2005 County Surveyor found CIM down 1.3' in good condition.

11-4-2005 County Surveyor found CIM down 1.3' in good condition, took local ties and removed. Found 1 1/2" iron pipe in good condition down 2.9'. Took local ties and removed. Set 7' teslpar w/CIC down 0.5' from ties taken from CIM. CSD with concrete nail south side of PP #39546 east 28.11'.

9-12-2007 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.