Certificate of Location of Government Corner

ID#: 732105 **Description:** SEC COR 20 21 28 29 73 **Date Set:** 11/3/2005 **County:** Olmsted

Section: 21 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' west of centerline of N-S twp road and 13' north of centerline of driveway east
120d in 30" Oak E 33.61'
This corner is located by GPS reference stations "Adler & Hidden Hills"

Corner History:

1853 Gov't Notes, W.B. Yerby, 80.00 Set section corner post. Planted Osage Orange N&W and SE of trench.

4-1857 & 5-1876 T. Hunter, P.23 No.36 used corner 16S M&L 19.89 (1312.74).

4-1858 T. Hunter,Pg.54, No.78 - Shows measure north 39.69 chains.

5-1859 T. Hunter, P. 60, No. 86 - Meansure north 39.92 chains to 1/4 post. 1/16 W20.02 chains M&L to 1/4 post. 1/16 S20.03 chains M&L to 1/4 post.

6-1896 T. Hunter, P.602, No.547, corner found by measure from stone south 19.89 (1312.74). P.23 & measure from S1/4 21 39.901/2 then found stake. Set new stake with 2x7/15x24 stone on west side of stake. Bearing Trees: 8" Burr Oak S35°W 281/2 links. 16e set stone 4x9x14 M&L 19.951/4.

3-1900 W. Fraser P.661 No.588 found stone. Set iron at 1/16th west M&L 19.88

3-1909 C. Armstrong, P.120 B found limestone as corner. 16n set limestone 6x12x16 M&L 19.871/2 (1311.75).

7-1923 County Highway Department Book #31, Pg.21 - Stone used by County.

6-1961 J. Kerr set CIM over iron rod.

10-20-2005 County Surveyor found CIM down 1.4' in good condition.

11-3-2005 County Surveyor found CIM down 1.2' leaning SW. Took local ties and removed. Found 1/2" pipe down 3.0' in good condition. Set 5' telspar pipe w/CIC down 0.4' at pipe location. Updated all ties and distances.