Certificate of Location of Government Corner

ID#: 732106 **Description:** 1/4 SEC COR 20 21 73 **Date Set:** 11/4/2005 **County:** Olmsted

Section: 21 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls under N-S fence
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.00 set sec post. Burr Oak 13" N44 W32 links.

4-1858 T. Hunter, Pg.54, No.78 & P.55 No.79, used corner. Measure west 40.00 chains to cen sec 20. 16E set corner at M&L 19.72 (1301.52). 16c SW1/4 measure north 19.83 (1308.78), east 19.72 (1301.52). Measure south 39.69 (2619.5).

5-1859 T. Hunter Pg. 60 No. 86 shows 1/4 post. 1/16 west 20.0 chains M&L to cen. Sec. 20. Measure south 39.92 chains to sec. Corner.

6-1896 T. Hunter P.602 No.547 corner gone, Bearing trees gone.

3-1900 W. Fraser, P.661 No.588 drove iron stake M&L 39.80 (2626.8'). 16N drove iron stake M&L 19.90 (1313.4) (Now gone 10-31-72). 16C NE1/4 20 drove iron stake inter lines.

1909 C. Armstrong P.120, B found limestone & recorded iron bar at 1/4 20-21, Set limestone 6x12x16 at 1/16 M&L S 19.871/2 (1311.75).

6-1958 J. Kerr set 1/2" rod M&L 2626.8

11-1-1972 County Surveyor set 3/8"x4' rod by stone found.

5-16-1974 County Surveyor set CIM over 1" rod - C.I. Set 1" deep - 2' east of N-S fence. Set corner by midway & line as per W. Fraser survey. 0.32' E of stone found in 1972; removed boulder and set it next to fence. Set steel fence post on N.E. side of CIM. Meas. N & S.

5-24-1990 County Surveyor found CIM 12" deep. Falls under N-S fence with fiberglass post on north side with 3" wood post with birdhouse attached on west side. Set sign & post 2' south in fenceline. Falls ± 300 south of house # 3472 in Hidden Hills.

10-19-2005 County Surveyor found CIM down 1.5' in good condition.

11-4-2005 County Surveyor removed CIM and found 1" rerod down 3.3' in good condition. Removed 1" rerod and set 4 1/2' telspar pipe w/cast iron cap up 0.1'. Set post w/sign.