Certificate of Location of Government Corner

ID#: 732204 **Description:** 1/4 SEC COR 22 27 73 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 22 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 7' west of centerline of CSAH 11 and 22' south of centerline of field driveway west
The monument is down 1'
Reference pipe W 43.97'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.00 set temp sec post west on true line between sec. 22&27 8° 56'E. 39.98 set section post. Burr Oak 9" N70 E83 links. Burr Oak 6" S28 W211 links.

1965 J. Kerr, Set corner at S22. 16 East set rod M&L 1317.7. Small hole top of 18" field culvert, south end ENE 41.67. Punched cross N end 18" drive culv. NW 47.58. Corner lies 7'W of center of new road grade. Measure west to section corner 2621.2. 1/16 north rod in co. rd. M&L 1313.25. 1/16 east of above 1/16 c SE1/4 22 set iron as corner. M&L 1319.4 on E-W 1/16 line of SE1/4 S22. 1/16 east of above 1/16 1/2" rod M&L 1314.4 on N-S section line.

6-14-1966 J. Kerr set CIM over point set in 1965 on E-W sec. Line.

8-12-1968 J. Kerr set 3/4" rod riser. CIM so deep now(11').

7-28-1989 County Surveyor found 3/4" rod in CR #11.

6-1994 County Surveyor found rod. Set reference point, 1" square pipe w/cap before cold recycling bituminous surface of CR #11

11-14-1994 County Highway Department set 1" square pipe w/cap at surface from 1994 overlay tie out

10-18-2005 County Surveyor found 1" square pipe w/eroded cap at surface in good condition. Replaced cap.

5-20-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.