Certificate of Location of Government Corner

ID#: 732305 **Description:** SEC COR 22 23 26 27 73 **Date Set:** 11/4/2005 **County:** Olmsted

Section: 23 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 80.00 set steel post to cor. Section 22,23,26,27 made trench. Burr Oak 20" N12 W631 links.

5-1876 T. Hunter P.293, No.288 found original corner stake, measure east 39.94.

4-1900 R. Fraser, P.663 No.590, found fence same a P.293. Drove stake & set stone 3x6x18, no meas.
Field Bk 15, P. 41-42, Measure each short 15 links.

6-14-1966 J. Kerr, Found corner post. Set 1/2"x3' rod 1' south of post. Line & meas. From SW cor. 22 to above corner, 2635.4W to S1/4 22 & W 2621.21 to SW22. 16W set rod M&L 1317.7. 16N set rod M&L 1314.4.

8-28-1989 County Surveyor dug for T. Hunter stake and R. Fraser stone and stake. Found J.Kerr iron. Corner post to fence N & E was pulled out of the ground and lying down NE of iron, You can't determine post holes or any marks.

9-11-1989 V. Fangman used 1/2" iron in survey for City of Rochester flood control structure SR-2.

11-4-2005 County Surveyor found 1/2" rerod down 0.6' in good condition. Set 6' telspar pipe w/cast iron cap over 1/2" rerod up 0.2'. Set post w/sign.