# Certificate of Location of Government Corner

**ID#:** 732405 **Description:** SEC COR 23 24 25 26 73 **Date Set:** 9/21/2006 **County:** Olmsted

**Section:** 24 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls in centerline of CR 119 and 1' south of fence west
County highway disk in PP #19358 NW 82.23'
This corner is located by GPS measurement

**Corner History:**

1853 Gov't Notes, Yerby, 80.00 set section corner post. RPs- 10" burr oak N 5 W 157 links, 12" burr oak N32 E145 links, 10" burr oak S70 E88 links, 9" burr oak S65 W 25 links.

5-1867 H.E. Horton, Pg. 84 No. 128

5-1875 T. Hunter P.242, No.243, found original corner. 16 east set stake M&L 19.831/2 (1309.1).

9-9-1968 J. Kerr dug extensively with backhoe, found post hole. Set CIM over 3/4"x30" pipe at this location.

2-20-2002 County Surveyor found CIM down 1.2' in good condition.

9-21-2006 County Surveyor found CIM down 1.4' leaning NW, took local ties and removed. Found 3/4" pipe down 3.2', took local ties and determined CIM was leaning .1' north and 12' west. Set 6' telspar w/CIC over pipe down 0.5'. Disc in PP #19358 NW 82.23'.

3-24-2010 County survey crew found CIC on telspar pipe up 0.1' in good condition. Drove monument down 0.5'.