Certificate of Location of Government Corner

ID#: 732504 **Description:** 1/4 SEC COR 25 36 73 **Date Set:** 9/28/2006 **County:** Olmsted

Section: 25 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' south of centerline of E-W twp road and 9 1/2' east of fence south
Bottle cap in E side CP NNW 40.33'
County Survey Disk in N side PP #49499 SE 99.72'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 40.00 set temp section post west on true line between section 25&36 8° 57' east. 39.99 set section post in mound, made trench, & planted osage orange seed N&S of trench.

9-1863 P.C. Compton Pg. 77, No. 115 Shows 1/4 corner used to set 1/16 east M&L to section corner east 25-36.

5-1872 T. Hunter Pg. 205, No. 213 found stake, set stone 2x7x15. Measure west 39.66 to stone set from stake. 16 east set stone 2x6x12 M&L 19.75 (1303.5). 16 south set stone 2x4/8x14 M&L 19.86 (1310.76).

4-1874 T. Hunter, P.242, No.243 found stone set P.205, 16 east found stone P.205.

8-21-1968 J. Kerr set CIM over original stone & iron. Corner lies 6' south centerline road - 9.7' east of fence south.

9-25-2006 County Surveyor found CIM down 1.2' in good condition. PP to the SE gone and corner post to the SW down, bottle cap in corner post to the NNW ok did not check ties.

9-28-2006 County Surveyor found CIM down 1.2' in good condition, took local ties and removed. Found stone down 2.9' but was dislodged by shovel, no ties taken. Found 3/4" iron rod down 4.0' took local ties and removed. Local ties showed 0.2' north difference in local ties. Set 6' telspar w/CIC down 0.45' from local ties taken from CIM. CSD with concrete nail in north side of PP #49499 SE 99.72', bottle cap in fence post end NNW 40.33' all other ties gone.