Certificate of Location of Government Corner

ID#: 732505 **Description:** SEC COR 25 26 35 36 73 **Date Set:** 9/25/2006 **County:** Olmsted

Section: 25 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' east of centerline of CR 119 and 2' north of centerline of E-W twp road
County Survey Disk in NE side PP NW 66.76'
County Survey Disk in SE side CP SW 78.59'
Punch mark on clamp in N end 18" CMP WNW 73.10'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 80.00 set corner post to section 25,26,35,36. Burr Oak 20" N20 W37 links. Burr Oak 11" N47 E45 links. Burr Oak 10" S34 E45 links. Burr Oak 10" S 18 W60 links.

5-1872 T. Hunter, P.205, No.213, found stake, set stone 2x6x14. Measure east 39.66 (2617.56 to stone set in place of stake, 16 south set stake 19.801/2 M&L.

8-10-1973 County Surveyor dug with backhoe at 1/16th South and found stone. Doubled line and distance from 1/4 Cor. 35-36 over 1/16th stone found and dug with backhoe. Road cut to rock. Found nothing.

5-3-1975 County Surveyor reset CIM over a 1/2"x6" iron rod at line and measure from south.

9-22-2006 County Surveyor found CIM down 1.3' in good condition PP to the NW replaced, corner post to the SE now leaning SE, telephone box replaced, CMP is still there.

9-26-2006 County Surveyor found CIM down 1.3' in good condition, took local ties and removed. Found 1/2"x6" iron rod down 2.8' in good condition, took local ties and removed. Ties from iron matched CIM. Set 3.2' telspar w/CIC from ties taken from CIM down 0.45'.