Certificate of Location of Government Corner

ID#: 732706 **Description:** 1/4 SEC COR 27 28 73 **Date Set:** 10/11/1972 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1 1/2' east of N-S fence and 9' south of fence west
RC Cola cap in SE side PP #24200 up 3.7' NNE 40.36'
Pepsi cap in PP #24201 NNW 37.3'
Green plastic disk in stub PP NNW 1.12'
Green plastic disk in W side PP NE 6.41'
Green plastic disk in E side stub PP CP N 8.95'
Sign on CP 1 1/2' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.0 set section post. Burr Oak 10" N60 W237 links. Burr Oak 10" S88 E247 links.

4-1857 T. Hunter P.23 No.36 set center 28 & marked Bearing trees.

5-1889 T. Fraser, P.429, No.417 set stake & stone 5"x10"x15" M&L 39.811/4 (2627.62). 16 west set stake & stone 2"x12"x20 M&L 20.0. Bearing trees - 8" Black Oak S40°W .11 1" Burr Oak N 85°E .2.j

1962 J. Kerr assumed the corner as the corner post of the fences North and South and West.

10-11-1972 County Surveyor set CIM over stone found.

8-1996 D. Strange of Peoples Coop found CIM & iron near surface.

4-16-2004 Roger Brand found monument in good condition 1' east of N-S fence.

11-8-2005 County Surveyor found CIM down 0.3' in good condition.

7-6-2009 County Surveyor found CIM down 0.3' in good condition.