Certificate of Location of Government Corner

ID#: 732805 **Description:** SEC COR 28 29 32 33 73 **Date Set:** 10/18/2005 **County:** Olmsted

Section: 28 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 11' south of centerline of E-W twp road on curve
20d spike in SE side PP #20230 up 18" NE 83.5'
20d spike in S side PP #20231 up 3' WNW 223.58'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 80.00 set section corner post in mound, made trench, and planted Osage Orange seeds NW & SE of trench.

5-1856 T. Hunter, Pg.23 No.36 showed corner used (1/16th north 19.85)

5-1858 T. Hunter, Pg. 56 No.81, 1/16 North 19.85 chains M&L to 1/4 post.

1-1872 T. Hunter P.191 No.202 used corner, found 1/16 north set P.23 M&L 19.85.

5-1889 T. Fraser, P.429, No.417 found stake.

11-1892 T. Fraser, P. 499, No.470 found stake P.429, set stone beside it. 16 south set stone 3"x15"x26" M&L 19.93. 16 east set stone M&L. 16C NW1/4 33 set stone N-S 1/16.

11-1957 K. McGhie set a 5/8" pipe as the corner by line and measured from the South. RPs- spike pp ENE 95.3', spike corner fence post WSW 35.15', spike in corner fence post W 74.7'

10-17-1972 County Surveyor found T. Fraser stone, set CIM over iron, original stone south side.

7-1979 County Surveyor found CIM in good condition. Used in control survey.

11-1-1989 County Surveyor found CIM. Looks like its leaning south.

10-18-2005 County Surveyor found CIM down 0.4' leaning south. Removed CIM and found 1/2" rerod down 2.1' in good condition. Set 7' telspar pipe w/cast iron cap over 1/2" rerod down 0.4'.