Certificate of Location of Government Corner

ID#: 732904 **Description:** 1/4 SEC COR 29 32 73 **Date Set:** 6/15/1976 **County:** Olmsted

Section: 29 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' east of N-S fence
Spike in SW side 12" Burr Oak ESE 47.23'
Spike in SE side 9" Burr Oak NE 15.82'
Spike in W side 13" Burr Oak N 14.55'
Spike in W side 10" Burr Oak NNW 34.57'
Spike in SW side 17" Burr Oak NW 45.07'
Post w/sign 1' west
This corner is located by GPS reference stations "Payne A & B"

Corner History:

1853 Gov't Notes, Yerby - 40.00 set temp steel post west on true line between sec 29&32 8° 28' east. 39.961/2 set sec post, made trench. 12" burr oak N 42 E250 links.

5-1858 T. Hunter, Pg. 56 No. 81 shows 1/4 post.

1869 Thomas Hunter (railroad ties) 2345' South to center of RR tracks.

5-24-1876 T. Hunter Bk.4 Pg.123 - used corner.

11-1957 McGhie found nothing, set 1/2" rod M&L. RPs- Spike in 15" Oak NE 21.9'. Spike in 15" Oak NW 38.7'. Spike in 10" Oak NNE 34.2'.

1969 16 S, Sankstone Surveying Co. found rod.

11-29-1972 County Surveyor set 1/2" square bridge spike as temp cor. RPs-14.52 NE to 40D NW side 16" Burr Oak. 47.25' SE to 40d SW side 12" Burr Oak

6-15-1976 County Surveyor set CIM over 3/4"x14" square iron on E-W section line and 1/4 line from north. Removed McGhie iron 16.6' west.

11-14-1989 County Surveyor found CIM, set sign & post 1.0' W.

10-28-2005 County Surveyor found CIM at surface in good condition.