Certificate of Location of Government Corner

ID#: 733104 **Description:** S 1/4 SEC COR 31 73 **Date Set:** 11/18/2003 **County:** Olmsted

Section: 31 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 9 and 10' east of centerline of CR 155 north
County Survey Disk in W side TP SE 64.78'
Mn/DOT Control monument SE 87.20'
County highway disk in SW side TP #19135 NW 76.88'
This corner is located by GPS measurement

Corner History:

Gov't Notes, 40.00 set sec post. Burr Oak 10"N 24°W 285 links, dug trench.

5-1891 T. Fraser P.457, No.441 S31, State of MN Corner gone. Set stake & stone on south line 31.

6-1895 Thomas Hunter (P. 603 No. 545), County Surveyor didn't find above corner-claimed gone for many years. Ran the section line and set a stake by measure only for line South.

6-1896 Hunter P.603 No.545 S6 Hulburt, Coe, Brackenridge. Set stake by measure for line south.

1935 Set bridge spike.

1968 county highway department Bk277, 1 1/4" pipe in road as corner.

11-10-1972 County Surveyor found county highway department nail used as corner

5-16-1974 County Surveyor set CIM over 1/2" x 2' rod and stones found.

7-1979 County Surveyor found CIM in good condition. Used in control survey.

4-2-1986 County Surveyor found head of CIM broken off.

2-26-2003 County Surveyor found pk nail at surface. Do not know who set nail, checked with county highway department disc in pp #19135. Bottle cap in pp #40979 gone. Decision was made to leave pk nail at surface.

9-12-2003 County Surveyor removed pk nail and found CIM without head down 0.6' in good condition.

11-18-2003 County Surveyor found CIM with head broken off down 0.4'. Removed CIM and found 1/2" iron rod down 2.3'. Left iron and set 1" square pipe w/cap at surface from local ties taken from CIM.