Certificate of Location of Government Corner

ID#: 733305 **Description:** S SEC COR 32 33 73 **Date Set:** **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 13W **Monument Description:**

Reference Ties:

The corner falls 4' south of centerline of twp road east, 19' east of centerline of twp road south and 8' west of centerline of field entrance north
Top lug in E end 24" CMP SSW 21.98'
Punch cross in S end 36" CMP SE 33.07'
County highway disk in NE side PP #19087 N 34.81'
This corner is located by GPS measurement

Corner History:

9-30-1853 John Ball, Deputy Surveyor, measured west 80.00 chains between Sections 4 and 33. Set section post and drove charred stake. Built mound with trench & planted Osage Orange seeds SE and Apple seeds NE.

10-6-1857 J. Fellows, (Book A, Page 41, No. 63), Shows section corner.

5-9-1875 T. Hunter, County Surveyor, (Old Field Book No. 4, Pages 111A & 111B), used corner chained north to R/W of RR 20.25 chs. and 27.20 chs. east to center of R.R. tracks 25.95 chs. east to R/W of RR then 13.11 chs. from center of RR tracks. S. quarter corner of Section 33.

4-1-1878 T. Hunter, County Surveyor, (Book A, Page 333, No. 327), found remains of old stake in center of road in line fence north and 2 rods from the corner post. Corner undisputed. Set stone 16"x8"/3"x4" in its place.

8-26-1884 T. Hunter, County Surveyor, (Book A, Page 391, No. 382) found stone.

6-14-1899 W. Fraser, County Surveyor, (Book A, Page 658, No. 586) found stone in center of road

6-20-1935 County Highway Department, (Book 75, Page 8) found spike over flat limestone.

1937 County Highway Department found iron spike in center of small limestones. Set 1" drill steel. RPs - X in ring top culvert NW 5.85', Tack in FP SE 46.5'

6-1947 J. Kerr, County Surveyor, (Book 33, Page 33) corner SW 33 1" drill steel.

11-1950 County Highway department had 1"x4' steel bar as corner (not corner).

11-1951 J. Kerr, County Surveyor, (Book 50) did some measuring along the south line of section 33.

1963 County Highway Department corner still in place.

5-16-1974 County Surveyor dug with backhoe and found shattered limestone 7' deep. Set a piece of calf pen pipe as a riser with a 1/2"x24" rod under a Cast Iron Monument. New corner falls 3' west and 1' north of the C.H.D. rod. Removed C.H.D. rod.

7-1979 County Survey Crew found and shot Cast Iron Monument in control survey (1979 Remon Book, Page 103)

5-23-1989 County Survey Crew found Cast Iron Monument in new blacktop.

9-6-1995 County Survey Crew found Cast Iron Monument in good condition. Used corner in old CSAH No. 9 R/W establishment.

12-1-2003 County Survey Crew found Cast Iorn Monument down 0.6' in good condition.

12-2-2003 County Survey Crew removed Cast Iron Monument and found 1/2" rerod down 2.3' in good condition.

12-11-2003 County Survey Crew set 1" square pipe w/cap at surface at Cast Iron Monument location and measured its position using GPS.

4-24-2017 County Survey Crew found 1" square pipe w/cap at surface in good condition. Removed prior to road construction.