Certificate of Location of Government Corner

ID#: 733306 **Description:** 1/4 SEC COR 32 33 73 **Date Set:** 6/21/1990 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' south of poor fence east and 13' west of poor fence north
Spike in 13" tree SE 14.33'
Spike in 8" Elm SW 14.95'
Post w/sign 1' north
This corner is located by GPS reference stations "Kappauf B & C"

Corner History:

1853 Gov't. Notes Yerby, 40.00 set section post, made trench. Burr Oak 6" S65°E 222 links.

10-1857 J. Fellows - Pg. 41 No. 63 shows 1/16 south with measure 19.71 chains to south 32-33.

5-1872 T. Hunter, BK1 Pg. 31,32, stake missing, reset from witness tree. Set stakes on line every 40 rods on 1/4 line west for fencing.

8-1884 Hunter P.391, No.382 found stone. All Bearing Trees standing.

11-1892 T&W Fraser P.499, No.470, stake remains. 16N set stone 3"x15"x26 M&L. 16C NW1/4 33 set stone M&L. N. at 1315.38'.

4-8-1901 W. Fraser, County Surveyor (P.658, No.586) used corner. Chained W 20.021/2 set stake, then 20.021/2 chains and set stake, chained 19.98 & found stake 1/16 south east of fence drove new stake.

11-14-1927 J. Kerr B-3 P34. Found a wood stake, set L stone 2"x7"x18" (NO GOOD).

5-1957 McGhie found limestone 2'east of SE corner fence post. (NO GOOD)

6-1969 T. Ferguson, found above limestone (NO GOOD).

10-1972 County Surveyor Found the true corner by the line from the E. Set a 120D nail over stone down 6". RPs- Corner 5' south of fence running west, 10' west of poor fence running south, 14' west of fence running north, 15.1 ENE to 20D SE side 12" tree with J.Kerr stone grown into south side of tree roots, 14.3 SE to 40D on SW side 16" blazed cherry or hackberry.

5-1-1973 County Surveyor Note: The correct corner is 13.87' W and 5.65' S. of J. Kerr's stone.

6-6-1990 County Surveyor found stone found in 1972.

6-21-1990 County Surveyor set cast iron cap on telspar pipe in place of stone. Set sign & post 1.0' north. 6' south of fence running west and 13' east of fence running north. RPs- Spike in 13" tree SE 14.33', spike in 8" elm SW 14.95'. Set sign & post 1' north.

10-28-2005 County Surveyor found cast iron cap on telspar pipe up 0.1' in good condition.