Certificate of Location of Government Corner

ID#: 733404 **Description:** S 1/4 SEC COR 34 73 **Date Set:** **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 13W **Monument Description:**

Reference Ties:

The corner falls 4 1/2' north of centerline of CSAH 9 and 1' east of fence south
This corner is located by GPS measurement

Corner History:

9-30-1853 J. Ball, Deputy Surveyor, measured west 40.00 chains between sections 3 & 34. Set section post with charred stake and built mound with trench. Planted osage orange seed SE and apple seed NE.

5-15-1876 T. Hunter, County Surveyor, (Book A, Pg. 292, No. 287), found stake in mound and left as found. 1/16th north set stake M&L at 19.87 chains. 1/16th west set stake M&L at 19.89 chains. 1/16th center of SW 1/4 Section 34 set stake M&L at 19.88 1/4 chains on N-S 1/16th line.

12-31-1937 County Highway Department, (Book 88, Pg. 8), assumed corner and set bridge spike at PI Sta. 159+60.9. RPs - Spike in Oak S 39.7', Spike in TP NE 45.2', Spike in FP NE 81.6'

6-28-1949 J. Kerr, County Surveyor, (Book 42, Pg. 19), set 1" rerod inside 1-1/2" pipe. Corner falls in line with fence south. RP - Center of west of two trees S 37.5'

1957 McGhie & Betts found 2" pipe with 1" rerod inside down 1.5'. Set 1/2" rerod at surface over it. RPs - Spike in twin 15" oak S 37.3', Spike in TP NW 42.85', Spike in TP NE 52.55'

4-3-1973 County Surveyor found no sign of corner, but found 2 original McGhie & Betts references. Set small nail from references and took additional RPs. Believe corner still in place, but too deep to register with locator. Small nail falls 6' NNW of centerline of CSAH 9. RPs - Shank of large PK nail in top of CP S 54.87', Punch hole W end field culvert SW 57.4', Punch mark in lug of apron E end field culvert SSW 47.6', Punch mark in lug of apron W end field culvert NE 69.41'

7-13-1981 County Surveyor dug with backhoe and found mark which may be from J. Kerr's iron or stake used by T. Hunter. This spot fits with 1/16th corner stake north, found 7-16-1981. Mark falls 0.9' S & 2.5' W of nail found at surface.

7-28-1981 County Surveyor set Cast Iron Monument over a 5/8"x18" iron at location of spot that fits 1/16 corner north. CIM falls 4 1/2' north of centerline of CSAH 9 & 1' east of line of fence south. RPs - County Survey Disk in TP NW 42.01', County Survey Disk in CP S 63.91', Chisel + in clamp plate in E end CMP S 46.46', Chisel + in clamp plate in W end CMP SW 54.14'

12-1-2003 County Survey Crew found CIM down 0.7' in good condition.

12-2-2003 County Survey Crew removed CIM.

12-11-2003 County Survey Crew set 1" square pipe w/cap at surface at CIM location and measured its position using GPS.

4-24-2017 County Survey Crew found 1" square pipe w/cap at surface in good condition and removed prior to road construction.