Certificate of Location of Government Corner

ID#: 733506 **Description:** 1/4 SEC COR 34 35 73 **Date Set:** 5/6/2009 **County:** Olmsted

Section: 35 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

This corner falls under N-S fence, in line with fence east and 1 1/2' SW of CP
Sign on CP 1 1/2' NE
This corner is located by GPS reference stations "Moriarty A & B"

Corner History:

1853 Gov't Notes Yerby, 40.0 set section post in mound, made trench, & planted osage orange seed W & E of trench.

6-1873 T. Hunter, P.228, No.231, found stake by fence post in line of fence running N&S.

5-1876 T. Hunter, P.292 No.287, found stake. 16W set stake M&L 19.97 (1318.02).

1937 County Highway Department B88, P73 - Big limestone - no size - No Rp's - no known record of setting.

8-20-1962 J. Kerr found stone 3"x16"x30", left as found.

4-2-1973 County Surveyor found vertical limestone west of corner post. NOTE: on finding section corner N 26-27-34-35 on 8-29-1968 it was apparent by Co. Rp's that they didn't have recorded corner found. Co. Rp's - Pine NE 58.4', Oak SE 99.2'

11-9-2005 County Surveyor found 2"x6"x20" stone at surface broken in pieces and leaning south. Ties gone.

6-6-2007 V. Fangman used County Surveyor's location for survey in NW 1/4 section 34.

5-6-2009 County Surveyor removed remainder of broken and leaning stone and set 5' telspar pipe with Cast Iron Cap up 0.1' at computed position from GPS and traverse data.