Certificate of Location of Government Corner

ID#: 733604 **Description:** S 1/4 SEC COR 36 73 **Date Set:** 6/30/2005 **County:** Olmsted

Section: 36 **Township:** 107N **Range:** 13W **Monument Description:** Brass plug with punch mark

Reference Ties:

The corner falls 2.3' south of centerline of CSAH 9 and in line with fence north
County Survey Disk in NE side PP SE 117.40'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, John Ball, 40.0 set section post. West between 1 and 36. 40.00 chs. Set quarter post. Dug trench. Burr Oak 10" N321/2°W 541 links.

5-1872 Hunter P.205, No.213, Lawler, Corner missing. Stump found of Bearing Tree. Reset corner w/stone 3"x4"x8". 16W set short stake in center road M&L 19.98.

1966 J. Kerr, see cards for measurements

?? County Highway Department Rp's to S1/4 cor. 36

8-16-1973 County Surveyor dug extensively and found nothing and set nothing.

11-18-1974 County Surveyor set 1 1/4"x8" pipe flush with concrete.

7-15-2003 County Surveyor found 1 1/4" pipe at surface in good condition.

6-30-2005 County Surveyor set brass plug with punch mark at surface from coordinates. Monument falls 2.27' south of centerline crack of CR 9 and in line with fence north. CSD with concrete nail in NE side of pp no # SE 117.40'.