Certificate of Location of Government Corner

ID#: 733605 **Description:** S SEC COR 35 36 73 **Date Set:** 7/5/2005 **County:** Olmsted

Section: 36 **Township:** 107N **Range:** 13W **Monument Description:** Brass plug with punch mark

Reference Ties:

The monument is at the surface
The corner falls 0.5' north of centerline of CSAH 9 and 5 1/2' east of centerline CR 119 north
County Survey Disk in NE side PP NW 76.30'
County highway disk in NW side PP NE 78.17'
County Survey Disk in SE side PP SW 56.90'
This corner is located by GPS measurement

Corner History:

Gov't Notes - 80.00 set section post, built mound, made trench, and planted plumb SE and apple seed NE.

5-1872 T. Hunter, P.205 No.213 corner gone, no evidence of corner. Mulverhill avers fence S built when corner stood and south road was set 2 rods south of corner. Set stone 2"x15"x12". 16 east set short stake center of road M&L 19.98 to stone 3"x4"x8" reset from Bearing tree stump, marks plain.

6-1873 T. Hunter, P.228, No.231 found stone set P.205, West set stake for division of SE1/4 35.

1966 J. Kerr, Corner now iron rod in Blacktop, origin. McGhie - no Rp's J. Kerr took measures.

8-9-1973 County Surveyor dug and found nothing.

5-9-1974 County Surveyor set a railroad spike as the corner using Thomas Hunter's prorated measurements from the west and north.

11-18-1974 County Surveyor set a 1 1/4"x12" pipe flush with concrete.

7-15-2003 County Surveyor found 1 1/4" pipe at surface in good condition.

7-5-2005 County Surveyor set brass plug with punch mark at surface from coordinates. CSD on NE side of pp #42647 NW 76.30. Bottle cap on NW side pp #19257 NE 78.17' and CSD disc in SE side of pp no # SW 56.90'. Monument falls .47' north of centerline crack of CR 9 and 5 1/2' east of centerline of CR 119 running north.

9-20-2011 County survey crew found brass plug in good condition.