Certificate of Location of Government Corner

ID#: 733606 **Description:** 1/4 SEC COR 35 36 73 **Date Set:** 9/28/2006 **County:** Olmsted

Section: 36 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3' east of centerline of CR 119 and 1' north of fence east
Ground wire in W side PP #19268 NNW 162.5'
County highway disk in E side PP #19267 SW 74.27'
County Survey Disk in S side fence post E 47.01'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.0 set section post, made trench. Burr Oak 6" S45W116.

5-1872 T. Hunter, P.205, No.213 corner gone and Bearing Tree gone. J.W. Livingston avers that corner post set by Barly 16 years before was in original mound close to corner then standing. Found remains of old post in center road. Set stone 4"x4"x16" where old post stood. 16 east set stake M&L 19.981/2. 16 north set stake M&L 19.801/2. Parties involved aver to set stone later a 1/16 cor.

6-1873 T. Hunter, P.228 No.231 found stone center road P.205, set stake west at 14.931/2 (985.7).

8-21-1968 J. Kerr found stone, P.205, 28.9' south of 20' offset. Found part of wood post below stone. Set CIM over stone and 12" steel rod. Corner lines exactly with fence running west. Measure CIM at center to stone found. Measure north 2640, set nail sec NW36 3/4"x30" pipe up 4" under fence west 100.0'.

5-29-1970 County Surveyor, measure west, set nail in line fences S&W at 2627.5'.

8-9-1973 County Surveyor dug for 1/16 stone North of 1/4 35-36. 1" knot up 2.2' on east side pp #19272 NNW 82.65'. Found stone and stake. Set 1/2" rod over stake not stone. Stone down 3' in center road. Corner 16 north of former point, no nail ever set.

1975 County Surveyor dug by 1/16 stone east. Found nothing, reset rod on east edge of stone.

9-28-2006 County Surveyor found 1/2" rod w/plastic cap down 0.2', cannot read cap but rod in good condition, took local ties and removed. Found CIM down 1.1' in good condition, took local ties and removed. Found 2x4x? Stone down 3.0' in good condition, ties matched. Set CIM at its original location down 0.45'. CSD w/concrete nail in south side of fence end post east 47.01'. Disc in PP SW 74.27', pipe to the west bent and leaning, removed. Did not check ground wire.