Certificate of Location of Government Corner

ID#: 740305 **Description:** SEC COR 3 4 9 10 73 **Date Set:** 11/10/77 **County:** Olmsted

Section: 03 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 20' west of N-S fence, 3 1/2' north of fence east and 9' south of fence west
Spike in E side 5" Cherry NNW 12.66'
NW corner of iron CP (at top) ESE 20.18'
CN&D in North side 10" triple Elm ESE 27.21'
Post w/sign 1' north
This corner is located by GPS reference stations "Bandel A & B"

Corner History:

6-1854 Gov't Notes M. Karrick 80.00 set post in mound with trench, pits. Charred stake & osage seed of each angle for corner to section 3-4-9-10.

4-1870 Robert Perry, County Surveyor, (P.108 No.147) found a new stake in mound with pits plain. Set a stone at the 1/16th South midway (1300.2') and on line to a stone set at 1/4 cor. 9-10 midway (2600.4') and on line between the sections corners. Set a stone at the 1/16th South of 1/4 cor. 9-10 also. Set a marked stake midway (1326.6') and on line at the 1/16th East of Sec. Cor. 3-4-9-10.

5-1911 Charles Larson (P.166B) found stone.

11-1916 John Kerr (P.252B), County Surveyor, could not find the corner. Ran and measured the line from 1/4 cor. 9-10 (not described) to N. Sec. Cor. 304 as set in this survey. Set a stone as the corner on this line and 2600' North of 1/4 Cor. 9-10. Measured East 2631.4' to 1/4 Cor. 3-10. Set a stake (shows stone in plat) at the 1/16th South.

2-1960 John Kerr (B.78 P.44) used the corner as set in 1916.

8-1966 John Kerr set a CIM at the corner set in 1916. Found the stone at 1/4 Cor. 9-10 and set a CIM over it. Also found a stone at the 1/16th South.

12-28-1972 The County Surveyor ran line from the 1/16th South of 1/4 Cor. 9-10 (found) over the 1/4 Cor. 9-10. Found Perry's stone at the 1/16th North approx. 10' West and 2.3' North of Kerr's 1/16th corner set in 1916. Continued this line North to Section Cor. 3-4-9-10 and doubled the measure from 1/4 Cor. 9-10 over Perry's stone at the 1/16th North. The point came approx. 21' West and 5.8' North of Kerr's CIM. Also doubled the line measure from 1/4 Cor. 3-10 over a stone found at the 1/16th West (and approx. 10' West and 2' North of the corner post believed set at Kerr's 1/16th. This point came 1.3' East and 1.1' North of the nail set by line and measure from the South.

3-29-1973 County Surveyor set a 1/2" rod as the corner at double the line and measure from 1/4 Cor. 9-10 over Perry's stone at he 1/16th North.

11-10-1977 The County Surveyor removed the CIM set by Kerr and reset it over the 1/2" rod set in 1973. The correct corner is 20.3' West and 4.3' North of Kerr's corner.

5-4-1979 County Surveyor set survey marker sign and post 1' NE.

4-4-1990 County Surveyor found CIM & sign & post in good condition.

4-26-2002 Mn/DOT Survey Crew found monument in good condition down 1 foot.

12-19-2002 County Surveyor found CIM down 1' in good condition.