Certificate of Location of Government Corner

ID#: 740606 **Description:** W 1/4 SEC COR 6 74 **Date Set:** 3/4/02 **County:** Olmsted

Section: 06 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S Twp road and in line with PP line West
1995 Ref. pipe W 74.55'
Concrete nail on north side of PP #24329 W 46.63'
Bottle cap on east side of PP #23993 SSW 104.6'
This corner is located by GPS measurement

Corner History:

Gov't Notes 40.00 set post & drove charred stake for quarter section corner. Built mound & dug trench SE Osage Orange, NE apple seed.

6-1870 R. Perry P.122 No. 157 found stone as east 1/4 section 1 during survey.

6-1873 T. Hunter P. 232 No. 234 found stone in center of road undisturbed. 1/16 west set stone 2x7x24 M&L 19.90 (1313.4) N 89º 38W. 1/16 south set stone 4x4/12x19 M&L 19.971/2 (1318.35) N1/4ºW. 1/16 center SE 1/4 sec. 1 set stone 2x8x20 intersecting lines.

6-18-74 T. Hunter P. 229 No. 232 found stone boulder in center of road.

12-3-1971 County Surveyor meas. from nail at W 6-7 E 1-12 found 1/16 fence east at 1313.5 R1318.35. Found 1/4 fence west at 2631.6 R2636.7 or 1318.1 from 1/16 fence east to 1/4 fence W R1318.1. Believe this nail close as meas. to W1/4 7 5271.6 R5273.4.

6-1-1972 County Surveyor found nail set 12-71 at 2631.6 North of 00 nail in intersection at W6-7 (could go 3.6 S) Meas. W from 00 nail to 1/16 fence S. near 1320', found 1/16 stone 2' deep, 2"x7" top. Set 5"x10"x12" boulder on top (1/16W). 1/16 3.0' E fence S-3 SW to center corner post 2', S to fence E figured 1/16 stone at 1317+from 00. Dug west, found broken LS 4"x7"x15" bottom half verticle & positive stone came 1.05' N and 3.9' W of 00 nail (w1/4 6). Stone 2' + N of fence E. Set 5/8"x12"+rod in place of stone with CIM above rod with orig stone pieces on S side base of CIM. 46.57 W to hard nail in 11/2" knot on north side of trans. line PP up 4" #24329. 104.6 SSW to pepsi cap on E. side of power pole 23993. Meas. w. to 1/16; measure S2631.6+4.0+1.05 = 2636.65±.

4-3-1975 County Surveyor set 10" CIM over previous one set in 1972.

8-31-95 County Surveyor found CIM in good condition 4' w of centerline road. Reference corner before road grading.

6-12-97 County Surveyor set 120d spike from ref. pipe. Corner falls in centerline N-S Twp. road. In line of PP line running west.

2-20-2002 County Surveyor found 120d spike removed. Found CIM down 2.3', removed 21" CIM, reset 60d spike down 0.3'

3-4-2002 County Surveyor set 5' telspar w/CIC over 60d spike down 0.5'

3-18-2004 County Surveyor found telspar pipe with CIC in good condition down 0.5'.