Certificate of Location of Government Corner

ID#: 740704 **Description:** 1/4 SEC COR 7 18 74 **Date Set:** 9/9/2005 **County:** Olmsted

Section: 07 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of 55th St NW and 159' west of centerline of 55th Ave NW
This corner is located by GPS reference stations "Bear A & B"

Corner History:

1854 Gov't Notes, M. Karrick 40.00 set temp. 1/4 section post E on true line between sections 7&18. 38.10 set 1/4 section post in mound with trench, pits, charred stake, & Osage Orange seeds NE & SW.

6-1857 John Fellows Pg. 28 No. 44 Used 1/4 corner to set center sec. measured east 39.75 chs. Meas. south 79.74 chs. to 1/4 cor. 18-19.

5-1876 T. Hunter P. 295 No. 290 found stone set by Perry in survey S 18 unrecorded. Having been set on line notes say midway between E&S meaning S line S7. 16 east stone set by Perry. Set temp point midway for line north 19.881/2 (1312.4') M&L.

7-1890 Thomas Fraser P.445 No. 430 found stone 4x11x24 set by Perry. Set 1/16 stone east & west of Perry survey. Stone in line fence north & 2 rods from corner post.

11-16-1971 County Surveyor ran line on 18.35' offset. West at center 7 stone found & 1/16 stone found north of center 7 and con't line south. Found recorded 1/16 L stone, 2/3x6/20 at 1322.0 R1322.31. Set nail at 2644.0 and line of center & 1/16 N. corrected to true line. Nail came 2' W. of fence north. 29.95 to bolt head on W. side 21/2" angle post. 76.7 ENE to 120D on SSE side SE'ly of 24" turn cottonwood trees up 4' RP to 1/16 stone north. Set 10" piece of No. 6 copper wire deep on east side of stone - cap stone down 12" ± 50.55 2'E of N. to conc. nail in knot on w. side of cedar post.

6-6-1972 County Surveyor found pieces of limestone in ground down 4' about 87' east of line of center & 1/16 north of center. Set CIM with 11/4" x 30' driven where stone sat. 1/16 stone north of center in solid undisturbed soils while center 7 and 1/16 south in soft moist fence rows.

4-1975 County Surveyor set a new 10" monument over monument set in 1972, no additional references taken.

11-20-1989 County Surveyor found CIM in good condition.

3-19-2002 County Surveyor found CIM down 0.5' in good condition

7-8-2004 County Surveyor found CIM down 0.5' in good condition. Tied out corner for road construction.

9-9-2005 County Surveyor set 1" square pipe w/cap at surface from 2004 tie out.