Certificate of Location of Government Corner

ID#: 740705 **Description:** W SEC COR 7 18 74 **Date Set:** 4/7/75 **County:** Olmsted

Section: 07 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2 1/2' East of centerline of 60th Ave NW South and 2 1/2' North of centerline of twp road East
County Survey Disk on NE side PP#24073 SE 58.37'
County Survey Disk on NW side CP NE 63.43'
County Survey Disk on SW side cut off PP CP NW 48.6'
This corner is located by GPS measurement

Corner History:

Gov't Set post & dug channel, stake corner to sections 7-12-13-18. Notes Built mound & trench. Planted SE Osage NE Apple Seeds.

6-1870 R. Perry P. 122 No. 157 found stone monument undisturbed. 1/16 N. set stone 4x5x22 M&L 19.971/2 (1318.35) 1/16W. set stone 51/2x51/2x17 and stake M&L 19.99 (1319.34) 1/16 Center SE1/4 12 set stone 5x5x15 M&L 19.981/2 (1319.01) N-S 1/16.

7-1890 Thomas Fraser P.445 No. 430 corner comes in 4'. Set nothing. See page by T. Fraser 1890. Copy of R.J. Perry survey 12/18 - 7-1871.

12-3-71 County Surveyor - Set nail in center of crossroads - road west abandoned for years, now field road. Used nail as 00 Center north. Set nail at 1317.0 in line fence west R1318.35. Continued line north to nail set as W 6-7 E 1-12. Meas. 2640 R2636.7. Meas. from nail to W 7-18 E12-13 west, set 120D at 1320 on north side road in line corner post at 1/4 12-13 Kalmar. Meas. north of 120D. Found recorded 4x51/2x18 L stone set as 1/16 corner.1870 at 1294.45 R1319.34.

6-6-72 County Surveyor found 1/16 stone west 2.6± E of 120D set at 1320. 1/16 stones N&S of W1/4 7 found. 16W stone 51/2x51/2"x17" leaning west. Replaced stone and set 1/2"x16" pipe riser. 177' WSW to punched cross in S end 5" old road culvert. 49.3 SW to center large 26" ± ash type tree. 43.0 SE to center large 24" ± burr oak tree.

4-7-75 County Surveyor set CIM over a 5/8"x14" rod on line from the north & double the distance from the 1/16 north making each 1/4 mile N=to 1318.03. Corner falls in T intersection 2.3' east of N-S centerline and 2.6' north of centerline E.

11-20-89 County Surveyor found CIM in good condition.

3-19-2002 County Surveyor found CIM down 0.4' in good condition

3-17-2004 County Surveyor found CIM down 0.6' in good condition.