Certificate of Location of Government Corner

ID#: 740805 **Description:** SEC COR 7 8 17 18 74 **Date Set:** 7/10/2003 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 14W **Monument Description:** 4 chisel marks on manhole ring

Reference Ties:

The corner falls on manhole in center of intersection of 50th Ave NW and 55th St NW
Spud in PP #36422 NE 58.8'
Face of 30" concrete PP NNE 103.94'
This corner is located by GPS reference stations "Holy Spirit A & B"

Corner History:

1854 Gov't Notes M. Karrick 80.00 set post for corner to sections 7-18-17-18 Aspham 6 N3 W27º Aspham 6 N63 E164 Dug trench.

7-1857 John Fellows Pg. 26 No. 41 Used sec. corner, Meas. N. 40.20 chs. Meas. east 39.78 chs.

7-1857 John Fellows Pg. 27 No. 43 Used sec. corner. 1/16 east 19.89 chs. M&L to 1/4 corner. 1/16 south 20.06" then 40.06 chs. to 1/16 south of 1/4 cor. 17-18.

5-1867 HE Horton, Pg. 84 No. 129 1/16 east 19.86 chs. M&L meas. north 40.06 chs. to 1/14 cor.

1890 T. Frazer at NE Sec. 18 found NE Bearing Tree - other B. Tree gone. Set stone 22"x9"x3".

5-1956 J. Kerr B63 P.11 parts S8&17. Corner gone. See 1941 Kerr notes Bk. 25 p.36-37. Set 4"x46" pipe filled with concrete as corner. Run & meas. sec. line between 8&17 total 5259.7.

9-24-1963 J. Kerr - Set CIM over 21/2x12" cast pipe. Spud in power pole NE 58.8 Spud in power pole SE 44.7 Center 24" burr oak NE 89.7 Center 22" burr oak SE 68.5

1941 Corner line in SW cor. intersection B25 P37. Found corner add.

12-20-1989 County Surveyor found PK nail at surface with PK nails 1.00's & 1.00 west. Dug with jackhammer. Found 1/2" rod down 13" found CIM set 10" CIM over old CIM.

8-17-1993 County Surveyor found CIM in good condition. Removed for sewer construction and took RPs. Ring to intersect for corner location.Spud in PP# 36422 NE 58.8'. Spud in PP# 36423 SE 44.76'. CSD in PP# 44570 SW 48.93', McGhie & Betts pipe SW 46.49. Face of 30" concrete p.p. NNE 103.94. CSD in pp#44570 SW 48.98'.

11-8-1993 County Surveyor intersected SE spud tie & NE spud tie for location. The pole face NE checked, p.p. sw & prop. cor. pipe SW were disturbed. Corner falls on sewer manhole. Chiseled mark on 4 directions of M.H.

3-14-2002 County Surveyor set out corner from ties and referenced with 2 points set in Holy Spirit property.

7-24-2002 County Surveyor set 1" square pipe w/cap as reference pipe and tied out corner for 2002 construction.

7-10-2003 County Surveyor set chisel marks on manhole ring north, south, east and west from 2002 tie-out.

8-14-2007 County Surveyor found chisel marks on manhole ring in good condition.