# Certificate of Location of Government Corner

**ID#:** 740906 **Description:** 1/4 SEC COR 8 9 74 **Date Set:** 3/11/2003 **County:** Olmsted

**Section:** 09 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

CN& D up 2.5' west side of 12" Pine ESE 29.16'
CN& D up 2.0' west side of 8" Pine SE 26.89'
Post w/sign 2' S
This corner is located by GPS reference stations "Teacher A & B"

**Corner History:**

6-1854 Gov't Notes: M.G. Karrick, Deputy Surveyor; 40.0 chs. Set post for corner to sections 7 & 8. Erected mound with trenceh and pits.

4-1870 Robert Perry Pg.108 No.147; Found corner post as the corner by"Statements of oldest settlers". Set stone at the 1/16 North.

6-26-1972 Roger Brand, County Surveyor, dug for post by doubling the line and distance from the North. (NW corner 9 over the 1/16 stone found). Found nothing and set a CIM.

2-24-1984 Roger Brand, County Surveyor, found the CIM down one foot, four feet west and one foot south of the corner post to the fences E-W-N. Set survey marker and post one foot north of monument.

3-17-1997 Gerald Stephas, MnDOT survey crew shief, recovered the 1972 CIM, updated the topography and measured new reference ties.

10-12-2001 Brand & Massey Surveying Inc. could not find CIM. They set 5/8" pipe w/cap #26371 as corner.

3-5-2002 County Surveyor found Brand & Massey 5/8 pipe. Removed pipe dipped found nothing, replaced pipe.

4-26-2002 Mn/DOT Survey Crew found pipe in good condition.

3-10-2003 County Surveyor found corner gone. New sanitary sewer construction may have destroyed corner.

3-11-2003 County Surveyor set 5' telspar pipe w/Cast Iron Cap up 0.2'. Set post w/sign 2' S.