Certificate of Location of Government Corner

ID#: 741004 **Description:** 1/4 SEC COR 10 15 74 **Date Set:** 5/23/00 **County:** Olmsted

Section: 10 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of 18th Ave NW and in centerline of 55th St NW
County Survey Disk in PP #K1204 SW 74.78'
County Survey Disk in PP #23557 NW 96.33'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - M. Karrick 40.0 set temp. 1/4 sec. post west on true line between sec. 10&15; 40.0 set 1/4 sec. post in mound V 8º 45' with trench, pits, charred stake & Osage Orange seed N. E. S. & W.

4-1870 R. Perry P.108 No. 147 found point as 1/4 cor., but didn't retain it. Meas. East 40.03 (2642 to stone set as sec. corner) meas. West 40.03 (2642 to stone set as sec. corner) both by testimony of oldest settlers.

6-1874 T. Hunter P.256 No.256 corner gone, replaced corner with small stake driven even with surface in middle road midway between fences. By a line from S1/4 15 over stone at center 15. Set in survey 4-1861 when all 1/4 posts were standing, this line inter. direct S. line of Sec. 10. Meas. long way from Midway as in P.108. (east 40.10 = 2646.6) west 39.67 (2618.22) Perry 2642.0 midway 2646.6 Meas. north 39.44 (2603.04') 5264.82

2-7-1878 See T. Hunter Book 5 Pg.41 Sec. 10 Found stake with stone by side. Meas. E 20.05 - 20.05 Meas. No. 19.70 = 1300.2

5-1911 Charles Larson B.166 B No mention of disc. of 1/4 10-15, but showed meas. to SW10 as 40 chs.

11-1916 J. Kerr P. 255 - Ran east from SW cor. 10, total mile 5278.0. Set large rock with + at 3958.5 - same at 1/4 10-15. 2639.0 Set 3" iron pipe at 1319.5 all on direct line. No disc of SE corner 10 anywhere in survey. Set center 10 midway on both 1/4 lines N-S 2609.5 E-W 2642.25.

1935 Co. H.D. - Old stake in center pile of rocks. Set 1"x2"x18" stake on top of old stake.

9-14-1963 J. Kerr set CIM over 3/4" pipe found, a stone, a large quarry stone set by Kerr in 1916.

1967 J. Kerr B.93 P.13 ran & meas. S. line of SE1/4 10 2635.35 and set 1/16 iron at 1317.67 which fell 22' E. of fence N. Ran N-S 1/16 line of SE 1/4 10. 2601.15 - set prop. corner 550' S. of 1/16 pipe which lies M&L 1316.07 between center 10 & E1/4, Ran N-S1/4 line 10 direct so. center 10 set at true inter lines - meas. from N1/4 10 to new center 2615.3 (Not 2609.5 as in 1916 survey) east from center 2632.14. Plat laid out in this survey adjacent to Trappers Hill plat with east line as 1/16 corner and ran 550' south and north line of plat 1/16 corner and iron 550' west-south west corner of plot 519' south and 550' east. See Pg. 13 B93.

1968 County Highway Department B.337 - Found CIM Sta. 52+58.68 Meas. south 2627.2, meas. north 2598.73. Corner is PI 0º34' left going north.

8-21-1969 J. Kerr removed CIM over pipe, set 1/2" rod in its place. Set rod 200' east on 1/4 line level road surface.

6-26-1970 County Highway Department 3/4" rod placed in subgrade. RPs-131.8 ESE to PP#40538), 72.84 SE to spike in pp #33807, 49.08 NE to spike in pp #39620, 54.15 NW to spike in pp #41071

12-28-1972 County Surveyor corner deep or gone. All Rp's gone, but SE PP#33807 and that may have been moved .16 east in place, additionalRPs-
43.0 NW to 7up cap on SW side Creso corner post, 60.2 SW to conc. Nail in top of 4" wood line brace post.

1-2-1973 County Surveyor Elec. meas. from SE 10 to SW 9 Cascade SE10 2635.32 S1/4 10 2631.80 S9-10 2635.80 (5/8" rod) S1/49 2634.29.

5-1984 Vince Fangman set 3/4" pipe over 1/2" rod at SE corner section 10.

8-22-1985 County Surveyor ± 1/16 corner found 2" pipe, took ties
11-1996 County Surveyor found pipe with plastic cap 6" deep in blacktop CR.112 12' north of centerline 55th St NW running west ± 15' north of centerline 55th St NW running East at intersection.

4-13-1999 County Surveyor found 5/8" pipe in good condition. Made ties.

11-12-1999 County Surveyor set pk nail at surface of blacktop 18th Ave NW and 55th St NW from ties taken in April.

5-23-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

1-10-2003 County Surveyor found 1" square pipe w/cap half gone at surface in good condition.

4-8-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-3-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.