Certificate of Location of Government Corner

ID#: 741005 **Description:** SEC COR 9 10 15 16 74 **Date Set:** 5/23/00 **County:** Olmsted

Section: 10 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 32' east of centerline of 25th Ave NW and in centerline of 55th St NW
Top center of hydrant NW 95.13'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - M. Karrick 80.00 set post for corner in mound with trench, pit charred, stake, & Osage Orange seeds of each angle.

4-1870 R. Perry P.108 No.147. Set a stone by testimony statement of oldest settlers. 16N set stone M&L 19.70 (1300.3 to 1/4 9-10 a stone set M&L 40.03 (2642.0 then 40.03 to stone set by this survey as 10-11-14-15 by statements of four settlers including Mr. Boardman.

6-1874 T. Hunter P.256 No.256. Found as set for Sec. Corner in survey No. 147 meas. East 39.67 39.67 (2618.22 to stake set from south).

5-1911 Charles Larson P.166B. Limestone by R.Perry 3 feet below surface.

11-1916 J. Kerr P.252 B. Quote - Started random line No. 3 at 1/4 9-10, ran south found 1/16 corner at 1297. Reset stone at SE of Sec. 9 and took bearing tree.

6-1935 J. Kerr Book 10, Pg.7. Found corner. Stone removed, but broken crockery and glass at bottom. Ran line W1/2 mile & set stakes 33' south.

7-15-1935 Co. Hwy. Dept. - Corner lost and County Highway Department assumed point equal from 1/4 corners east & west to the same meas. as from that 1/4 corner to section corner beyond. SW 9 stone monu. with old rotted stake in E. side 4' deep. S1/49 found iron pipe m top of stone with broken glass. SE 9; SW10 - Used assumed point on above meas. S1/4 10 - Found old rotted stake in center pile of rocks. SE10, SW11 - found stone monu. broken glass & rocks line from East E over D fell 1.0' North of line from west A over B. Measure overlap .5'.

12-28-1972 County Surveyor found limestone 3"x4"x18"± with chisel point top .7' W of lower fence wire of N-S fence, 2.2' south of lower fence wire E-W fence. Offset 125' west at 1/16 stone and CIM at 1/4 9-10. Found corrected meas. between CIM & 1/16 stone 1299.9 (R. Perry 1300.3). Set large PK at at double this meas. & corrected exact line which fell S of centerline new blacktop mat and 8' E of fences N-S both 1/4 9-10 & 1/16 stone above same .7' west main line fences at those points.

3-30-1973 County Surveyor reran line, checking 125' offsets. Drove 5/8"x12" rod as final corner in black top. Removed PK.

8-7-1985 County Surveyor Found 5/8" iron rod in blacktop 55th St. NW just before regrading on 55th St. NW.

8-22-1985 County Surveyor - At 1/16 corner ± east, found a 2" iron pipe. Pipe found by City of Roch. engineer crew staking for regrading on 55th St. NW (Possibly set by Kerr in 1916 or 1933). Top of pipe ± 8" deep from blacktop surface. Used dozer and dug ± 1 foot deep on each side of pipe, found nothing. Dug 10' N&S of pipe and 5' E to 3' West. Evidence of old road in cut. Road bank north is ± 6' higher than road surface. Left pipe inplace. Pipe is ± 4' west of steel post running north.

9-13-1999 County Surveyor found pipe in good condition. Set ref pipe and tied to corner.

11-9-1999 County Surveyor set p.k. nail from ties.

5-23-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

5-10-2002 Mn/DOT Survey Crew found monument in good condition.

8-27-2002 County Surveyor found 1" square pipe with cap in good condition.