Certificate of Location of Government Corner

ID#: 741006 **Description:** 1/4 SEC COR 9 10 74 **Date Set:** 8/9/1966 **County:** Olmsted

Section: 10 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls at SW corner of Schmidt Park and in line with E-W fence South of house #6216
SW corner shed WNW 51.81'
SE corner shed NW 37.50'
NE corner shed SW 67.68'
This corner is located by GPS reference stations "Schmidt A & B"

Corner History:

6-1854 Gov't Notes - M. Karrick 40.00 set 1/4 section post in mound with trench, pits, charred stake and Osage Orange seeds N, E, S & W

4-1870 R. Perry P.108 No.147. Set stone as 1/4 cor. meas. of N. line 20.10 1/4 line. 20.06 and S. line 20.011/2. Makes it set M&L 39.40 2600.4. 16N set stone M&L 19.70 (1300.2). 16S set stone M&L 19.70 (1300.2). 16E put post in, made mound & pitts. M&L 20.06 (1323.96 to point found as cen. section 10, but not retained. 16W put a stake M&L 19.94 1316.04 to center 9 a stone set.

6-1874 T. Hunter P. 256 No. 236. Used corner of fence running east as corner for line east to set center. Post assumed as being set and stone removed.

5-1911 Charles Larson P.166 B. Found limestone. Meas. west 39.88 2632.08.

11-1916 J. Kerr P. 252B. Survey states "Started on the E1/4 9 and ran a random line north 11/2 miles. Final meas. 7759 finally set NW10 at 2600 making north 1 mile. 5159 (Dr. Lufgren survey N.78 P.44 S3 line meas. very carefully north from sec. corner set 5154.0 on this exact line direct to N 3-4. Ran line S. of 1/4 9-10 (undescribed) P. 253 "found 1/16 cor. at 1297. (corner not described) Reset stone at SE9 at 2600 or 1303 from 1/16 corner. No description of events leading to "reset" of this corner, or of corner itself (see 9-10-15-16, 6-1935 survey). Page 257 - ran measure from 1/4 10-11 west to 1/4 9-10 5284.5' - set center 10 midway 2642.25. Also set center 10 midway 2609.5 on N-S 1/4 line.

8-9-1966 J.Kerr found 6"x24"x30" stone believed set by Kerr in 1916 as NW cor. 10. Set CIM in its place and meas. south & found 1/16 fence running west at 1297.0 and stone at 1/4 9-10 at 2595.2 where CIM set 8-9-1966. R1300 and 2600 found perfect limestone in perfect line fence east and very little west of fence south. Drove 1/2"x3' rod on SE side of stone with CIM over center stone - set long Model T Ford steering column shaft under fence east; driven near ground level E 50.0'. Corner used in Qualey Trappers Hill survey to set center B93 P13 10 at true inter. lines.

10-7-1986 County Surveyor found CIM on top of ground at fence corner of fence E&S. Dug down to stone with 1/2" rerod on SE side stone down 2'. Reset CIM over stone & checked at 50.0 from Kerr shaft under fence east. Set survey marker, post & sign 7' north. Corner in line with fence east and 2' west of fence, south corner post gone.

11-20-1989 County Surveyor found CIM in good condition. Now on back lot line of new houses. Reset sign, post 0.8' north.

3-17-1997 Gerald Stephas, Mn/DOT Survey Crew Chief, recovered the 1986 cast iron monument, updated the topography and measured new reference ties.

5-10-2002 Mn/DOT Survey Crew found monument in good condition at SW corner of Schmidt Park and in line of E-W fence.

8-27-2002 County Surveyor found CIM in good condition.