Certificate of Location of Government Corner

ID#: 741104 **Description:** 1/4 SEC COR 11 14 74 **Date Set:** 10/16/2017 **County:** Olmsted

Section: 11 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 22' south of centerline of west bound lane of 55th Street NW in median
The monument is down 0.2'
This corner is located by GPS reference stations "Porath A & B"

Corner History:

6-21-1854 Michael Karrick, Deputy Surveyor, measured east (Variation 8°11'E) on random line 40.00 chains between Sections 11 & 14 and set temporary post. Measured west (Variation 8°) on true line 40.00 chains between Sections 11 & 14 and set 1/4 Section post. RPs - 12" Bur Oak S67°E 245 links (161.70'), 8" Bur Oak N63°W 115 links (75.90').

2-4-1878 Thomas Hunter, County Surveyor, (Book A, Page 329, Survey No. 323 and Field Book #5, Page 40) found 1/4 post missing and no remains of it could be found by dilligent search and digging. SE witness tree standing and NW witness tree missing. Found by trial that the bearing given in the Field Notes for the SE bearing tree was entirely wrong, as it would place the 1/4 post at least six rods south and west of where it should stand and where it was known by Mr. Philo Boardman and others to have stood within a few years. Measured section line and set 3"x8"x20" stone midway between section corners and 245 links from SE bearing tree. He ran the line west to SW Section Corner 11 and in doing so he followed exactly on the line of the old blazes through the timber. SE Witness tree is now S30°E 245 links (161.70'). 1/16th West set marked stake midway and on line at 19.98 chains (1318.68') to Section Corner 10, 11, 14, 15. RPs - 6" Rook Elm S88°W 21 links (13.86'), 15" Water Elm S16°W 55-1/2 links (36.63').

1-3-1900 Robert Fraser, County Surveyor, (Book A, Pages 646-652, Survey No. 582) cound not find stone set by T. Hunter. Set temporary stake at 39.96 chains (2637.36') from SE Section Corner 11.

4-18-1900 Robert Fraser, County Surveyor, (Book A, Page 665, Survey No.591) dug and found stone and stake set by T. Hunter. Set new stake. RPs - House corner N33-1/4°E 129 links (85.14'), 10" Jack Oak N10°W 60-1/2 links (39.93'). 1/16th West set stake midway and on line. Did not look for stake set previously.

10-1-1901 William Fraser, County Surveyor, (Book A, Pages 646-652, Survey No. 582, Caption) 1/16th East set stone midway and on line at 19.98 chains (1318.68') to Section Corner 11, 12, 13, 14.

4-27-1954 John Kerr, County Surveyor, (Book 59, Page 16) found limestone down 5'. Set full length buggy axle over limestone. RPs - Spike in 12" Burr Oak N 38.85', Spike in 12" Burr Oak NE 40.05', SW corner house foundation NNE 84.7'.

4-27-1983 County Surveyor found 1/2" pipe w/cap PLS #1613 (Ken McGhie). Removed 1/2" pipe and found buggy axle down 2' in condition. Pipe was set over axle. Set Cast Iron Monument over axle. The corner falls on berm on SW side of driveway on curve from East to NW and in line with center of road farther east. Set post with sign 1.15' south and plastic fence post 0.5' west. RPs - Old spike in W side 14" Burr Oak N 38.85', Old spike in E side 14" Burr Oak NE 26.19'.

5-28-2003 County Survey Crew found Cast Iron Monument down 0.4' in good condition and measured its position using GPS.

5-31-2016 County Survey Crew found monument removed due to road construction.

10-16-2017 County Survey Crew set 4' telspar pipe with Cast Iron Cap down 0.2' at previously GPS location after road construction. The corner falls 22' south of centerline of west bound land of 55th Street NW in median.