Certificate of Location of Government Corner

ID#: 741105 **Description:** SSEC COR 10 11 14 15 74 **Date Set:** 6/2/00 **County:** Olmsted

Section: 11 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in center median of 55th St NW
County Survey Disk in PP #29404 SW 79.78'
SW corner old house foundation NNW 83.65'
Center twin Cottonwood NW 94.7'
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: M. Karrick, Deputy Surveyor; 80.0 chs. Set post for corner. Erected mound with trench pits, charred stake and osage orange seeds at each angle. At 62.0 chs from south-Creek 8 links wide runs east.

4-1870 R. Perry Pg.108 No.147; Corner "D" established this point on statement of two of Mr. Stagus sons, Mr. Boardman & Mr. Fosenger and from appearences their statements are correct, and set a stone as section corner.

6-1874 T. Hunter Pg.256 N0.256; Corner not mentioned. 1/16 north set stake, 1/16 west set stake, 1/16 stake set in center SE 1/4 10.

2-1878 T. Hunter Pg.329 No.323; Corner gone. Set stone 2x6x16 deep with stone 2x6x16 on top.

8-1935 county highway department Bk.75 Pg.34; Found stone monument with bricks and glass.

8-1958 J. Kerr Bk.73 Pg.77; Geo Hayes survey; Found corner and used for line east. Set 1/16 east a 3/4" pipe. RPs- 115.5 NW to SE corner house foundation, 50.0 SW to 120D in 3' triple elm tree, and set 120D on section line at 1520' from the west.

9-1963 J. Kerr set CIM over pipe in place as corner and junk.8

12-1972 County Surveyor found CIM down 6". RPs-60D nail on SW side 16" butternut at 46.0 NW, 60d nail on SE side 12" pine tree at 39.75 NE, corner lies 8.0' east of eye line of west side house north. Found 1/16 west. New RPs-43.0 NW to 7up cap on SW side Creso corner post fence north, 60.2 SW to conc nail in top 4" wood line fence brace post.

1-1973 County Surveyor found 1935 county highway department cottonwood still standing and checks with CIM; rod set west at 1/6 corner on perfect line to 1/4 10-15.Found rod set by Kerr

9-1977 County Surveyor found 1/2" rod down 8" in new bit. Surface. Set 1" pipe over it flush.

9-1989 County Surveyor found 5/8" pipe with cap #11622. RPs-4.5' south to centerline of road, checked pine tree NE ok, butternut NW, nail must be grown over. Found 1" pipe ± 988' west.

4-13-1999 County Surveyor found 5/8" pipe in good condition. Set ref. pipe and tied in corner.

11-9-1999 County Surveyor set 120d spike in median of 55th St NW from ties made in April

6-2-2000 County Surveyor set 4' long telspar w/cast iron cap down 0.2'.

1-14-2003 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.