Certificate of Location of Government Corner

ID#: 741106 **Description:** 1/4 SEC COR 10 11 74 **Date Set:** 9/7/2007 **County:** Olmsted

Section: 11 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of 62nd St NW and 26' E of centerline of residential driveway north
Punch mark in N end 24" CMP NW 61.09'
Punch hole in S end 24" CMP SW 55.09'
County Survey Disk in NW side PP #53841 NNE 37.03'
1992 ref rod WNW 243.66'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - M. Karrick 40.0 set 1/4 section post in mound with trench, pitts, charred stake, & Osage Orange seeds NE & SW.

6-1874 T.Hunter P.256 No.256 found stone center road, avered as set by B.G. Boardman in center mound & pits. 16 west set stake M&L 20.041/2 (1323.0'). 16 south set stake M&L 19.731/2 (1302.5'). (See T. Hunter Book 5 p.41 Sec. 10 1878).

6-1900 R. Fraser P.646 to 652 No.582 found stone in center road at NE corner old school house, cellar remains, a pointed limestone. 16 north likely temp. point M&L 19.681/2 (1299.2).

10-4-1922 J. Kerr B-9 P.46 - pipe in basement.

11-1939 J. Kerr P.530 B found 11/4" pipe in north part of basement. Set irons east 577.5 and then 247.5 for school being 88' N&S from center E-W1/4 line.

8-1963 J.Kerr found pipe & set CIM now centerline road on private Boardman road. Spike in 8" boxelder S77.5. Disc in tele. pole NE 50.4. 16 west run line for Owaley. Didn't set pipe as 1/16 first time. Pipe reset now M&L 1316.07 B93 P13. Meas. north to NE cor. 10 2599.4 R2598.4.

6-14-1990 County Surveyor found CIM with broken top leaning south. 5' deep to top of CIM; dug down to pipe found by J. Kerr down 71/2'.

6-18-1990 County Surveyor set CIM over 1/2" rod at pipe location. Now falls in centerline of E-W Twp. road.

5-26-1992 County Surveyor - Set ref. rod on north shoulder of 62nd St. NW 15' north of centerline and in line with centerline 12th Ave. NW running so. At ref. rod < Rt (stub on top of light on radio NW of ref. rod) to 1/4 10,17 124º 52' 19.5". < Rt (same light) to prop. cor. 33' south of CIM. 132º 33' 06.5". To 1/4 cor. 10,11 (CIM) VA 90 03 11 dv 03. SD 243.665 HD 243.66. To prop. cor.VA 91 56 11" dro 6. SD 248.205 HD 248.06.

2-8-1999 County Surveyor found p.k. down 2 1/2" in blacktop.

6-10-1999 County Surveyor set survey marker nail at surface of blacktop.

1-14-2003 County Surveyor found survey marker nail at surface in good condition.

8-15-2007 County Surveyor found CIM down 0.9' in good condition. Checked ties.

8-16-2007 County Surveyor removed CIM and found 1/2" rerod down 2.6' in good condition. Removed 1/2" rerod.

9-7-2007 County Surveyor set 1" square pipe w/cap at surface at CIM position.