Certificate of Location of Government Corner

ID#: 741304 **Description:** 1/4 SEC COR 13 24 74 **Date Set:** 6/6/64 **County:** Olmsted

Section: 13 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' SE of CP of fences N & E
Spike & disc in 16" Burr Oak NW 27.00'
Spike in root of 12" Burr Oak NE 12.00'
This corner is located by GPS reference stations "Dodge B & C"

Corner History:

Govt. Notes M. Karrick 1854 40.00 set temp. 1/4 sect. post West on true line between sections 18-24 8º 32. Burr Oak N 10 W 743 Dug trench.

8-1876 T. Hunter P. 303 No. 298 found old stake, tested by witness tree stump. 1/16 East set stake M&L 20.10 1326.34' 1/16 south set stake M&L 19.99 1319.34' 1/16 center NW 1/4 24 set stone at inters. lines Measure east 40.10 2646.6'
Hunter Field Book says set stone 24"x6"x2" in place of stake found.

2-1878 T. Hunter P. 330, No. 324, 16 west found stake P.303 M&L 20.10. 16 north set temp. joint M&L 19.821/2, 16 center SW1/4 13. Set stone 5x7x20 with flange projections on 2 sides of it at bottom being set at inters. lines.

7-1960 John Kerr B81 P.42 Measure west 2650.46 set temp. point at 1325.32 - run E-W 1/16 line of SW 1/4 13. Set iron pin M&L. 1326.95 and 831.95 each of 1/16 - run N-S 1/16 set the iron pin also M&L 1310.83 did not know about stone so didn't search.

10-7-1963 John Kerr B87 P64 Found 1/2" rod 1/16 cor. M&L 1326.95 set 1/2" pipe north 344.3 of 1/16 - 344.95 north at SW cor. of NW 1/4 SW 1/4 13.

6-1964 John Kerr-Set CIM in place of stone on south hill slope about halfway up hill slope - piles of limerock about corner. Disc. 16" brook NW - 26.6 - Sp in side 10" from oak SW 7.37 Sp root 12" oak NE 11.75 - lies 1.75 SW cor. fence post.

1-10-90 County Surveyor found CIM in good condition.

12-16-1997 McGhie & Betts Found C.I.M. at the fence corner for fences running.

6-16-2003 County Surveyor found CIM up 0.2' in good condition.

12-1-2003 County Surveyor found CIM up 0.3' in good condition.