Certificate of Location of Government Corner

ID#: 741306 **Description:** 1/4 SEC COR 13 14 74 **Date Set:** 8/16/2007 **County:** Olmsted

Section: 13 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 11 1/2' west of centerline of N-S twp road and 52 1/2' S of centerline of quarry driveway west
Minnesota Highway Disk in N side 24" Burr Oak W 43.17'
Minnesota Highway Disk in NW side PP #34385 SW 30.54'
Minnesota Highway Disk in SE side 24" Burr Oak SW 45.19'
Post w/sign 23' west
This corner is located by GPS measurement

Corner History:

Gov't Notes M. Karrick 1854. 40.00 Set 1/4 sect. Post Burr Oak 12 N 76 W 473 Burr Oak 12 N 80 E 70

2-1878 Hunter P.330 No. 324 found corner set P. 329 1/16 east set boulder. 18"x16"x10" running to point. M&L 20.13 1/2 1328.9' 1/16 south set stone 24" x (18x20 at bottom)(12x2 at top) M&L 19.89 3/4 1313.25' Meas. North 39.90.

10-1948 J. Kerr B39 P67 found boulder NW Cor. 13, W 1/4 13 and boulder 1/16 east of W 1/4 13. Measure North 21636.0 with prop. cor. at 1326.45 set post by stone also run line north of 1/16 stone 2632.8 to 1/16 with p. cor. at 822.75.

6-1952 John Kerr B55 P25 run line E 1/4 14 west 2614.5 set 1 1/4" pipe at 1307.25 - RP 1/16 40D NE 22.0' 30" elm.

1954 John Kerr B59 P16 center 14 east 2614.5 E 1/4 13 North 2636 - NE Cor 14 West 2635.35 N 1/4 14 south 2628.25 - with pipe set at 1314.12.

9-1963 John Kerr Set CIM over 3/4"x18" pipe on west edge traveled road. 60D in 15" Oak W 43.0 - 60 D in 15" turn oak SW 45.5 120 D in 18" brook 55 W 104.7 - road now blacktop.

10-1963 John Kerr B87 P64 replaced 5/8" rod as 1/16 east of 1/4 13-14 M&L 1328.68 evidently did not find stone at 1/16. Set 1/16 south 120 D 1313.35 with iron 33' east.

4-1978 County Surveyor received survey data from M.H.D. filed in "Blue Book" at Center 13. Survey has coordinates on all corners in section 13. Plus center 18 (except SE) Meas. North 2635.68 to CIM South 2627.85 to CIM. East 2657.80 to rebar.

8-7-1996 County Surveyor - found 1/2" rerod 12" long 2" down on rock shoulder N-S blacktop road, we pulled rerod and dug down to CIM 14" deep the two positions didn't match so we left CIM as is to use in Photo Control Survey. E N-S East River Road East 11 1/2' Face of survey sign post West 22.8'

12-16-1997 McGhie & Betts Found C.I.M. 11.5' West of center line bituminous road and reference inplace.

6-16-2003 County Surveyor found CIM down 1.5' in good condition.

12-2-2003 County Surveyor found CIM down 1.3' in good condition.

8-16-2007 County Surveyor found CIM down 1.4' in good condition. Removed CIM and found 3/4" pipe down 3.2' in good condition. Removed pipe and set 6' telspar pipe w/cast iron cap down 0.4' at CIM location.