Certificate of Location of Government Corner

ID#: 741404 **Description:** 1/4 SEC COR 14 23 74 **Date Set:** 8/27/2007 **County:** Olmsted

Section: 14 **Township:** 107N **Range:** 14W **Monument Description:** 1" copper plug w/punch mark RLS #15809

Reference Ties:

Chisel hole & cross in SE cor. trans. pad NW 33.19'
NE corner of sludge thickening bldg. ± 3' above ground, corner of conc. block SSE 41.87'
NW of corner of sludge bldg. ± 3' above ground, corner of conc. block SW 76.72'
Back of curb N 9.53'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: M. Karrick; 40.0 set temp 1/4 section post west on true line between sections 14-23 V8°32'. 40.0 set 1/4 section post. RPs- 12" burr oak N 47 E 27, 12" burr oak S35 E 32.

5-1870 T. Hunter P. 179 No. 190, 16 south set stake M&L 19.871/2 (1311.75'), meas. west 40.22 (2654.52')

2-1878 T. Hunter P. 329. No. 323, 16 west set temp. stake M&L 20.091/2 (1326.3') 16 north set stake M&L 19.98 (1318.68').

1889 T. Fraser P.437, No. 424 - Found 1/16 corner north and center 19.99 north with Bearing trees to both.

1897 W. Fraser, P. 609 No. 554 - 16 west found stone M&L 20.09 (1325.94') from this 1/6 stone run line north 59.98 than east 20.01 to stone found on N-S 1/4 line.

6-1952 J. Kerr B. 55 P. 26 run line S 1/4 14 north across river total 2632.67.

8-1961 J.Kerr set CIM over 5/8" rod & junk.

11-1961 J. Kerr CIM in place - meas. west 2638.44 set 1/16 rod.

7-17-1969 J. Kerr west found limestone 18" deep, set iron by stone. Sp in 40" elm SW 35.1 - Sp in PP NW 44.5 - tele cable marker SE 91.0 - B55 P.26 J. Kerr shows line from cente south 2632.67, also shows S1/4 14 as 3/4" pipe.

9-21-1972 County Surveyor meas. line carefully 68deg. 1327.15. Record = 1325.94

9-26-1972 County Surveyor dug 9' deep entire area found 3/4 x 4' rod down 4' but no stone or stake anywhere.

3-23-1973 County Surveyor - Set 30"x3/4" square head bridge bolt as 1/4 14-23.

9-24-1980 County Surveyor Located square head bolt with post & sign about 1' north of bolt.

9-15-1981 County Surveyor; took ties to corner (bridge bolt). NE Cor. mostly N1/4 NE corner of bldg. SW 93.00. NE Cor. mostly E1/4 NE Cor. of bldg. SSW 93.81. Center of 5 pt. punch mark in flat iron on top of concrete foundation of round tank directly beneath NW1/4 seam SE 80.70.

4-26-1982 County Surveyor took ref. points for cut CSD in E. side pp S. 22.65 Spike in NE side pp 39.54 CSD in west side pp S. 22.64 CSD in SW side pp NW 39.53

10-10-1986 County Surveyor reset Cast Iron Cap on telspar pipe as corner from references taken on 9-15-81 corner .36 N of back of N. curb of road on north side sewage treatment plant, add ref. points punch hole in curb SW .70'. Punch hole in curb SE .70 to SE cor. (down .4 from top) conc. transformer slab WNW 31.13.

10-1986 County Surveyor Reset CIC/sq. pipe as corner from refences taken 9-1981; corner .36N of back of north curb of road on north side sewage treatment plant, addRPs- punch hole in curb SW .70, punchhole in curb SE .70 SE corner conc. Transformer slab WNW 31.13.

11-3-1992 McGhie & Betts set chiseled hole & cross in concrete road after constr. destroyed corner.

6-16-2003 County Surveyor found chiseled hole and cross in concrete.

12-2-2003 County Surveyor found chiseled hole and cross in concrete in good condition.

1-12-2004 WHKS found drill hole and cross in concrete road at Rochester Reclamation Plant in good condition.

8-27-2007 County Surveyor found chisled hole and cross in concrete. Tied out and set a copper plug with punch mark at surface.