Certificate of Location of Government Corner

ID#: 741706 **Description:** 1/4 SEC COR 17 18 74 **Date Set:** 4/29/2010 **County:** Olmsted

Section: 17 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 73' east of centerline of N-S twp road
The monument is down 0.1'
This corner is located by GPS measurement

Corner History:

7-1854 Gov't Notes M. Karrick, 40.00 set 1/4 sect. post in mound with trench, pitts, charred stake & Osage Orange seeds NE & SW.

7-1857 John B. Fellows Pg. 27 No. 43 used 1/4 Cor. from 1/16 south to 1/16 so. to 1/16 north shows 40.06 chs. then 20.06 chs. to No. sec. cor. 17-18.

5-12-1969 J.Kerr set CIM over sash weight M&L 2639.6, 4" below surface with glass & rock at base and crush rock 6" deep in pit over top of CIM. Corner comes in near center of east road ditch, centerline N-S road west 18.5'±; east edge of N-S road west 9.5'±, in east end road culvert S. 104.73, in south end field drive culv. 15" 10' N of W 43.38.

3-5-2002 County Survey Crew found CIM down 1.1' in good condition in East inslope of N-S twp road.

7-9-2008 County Survey Crew found CIM down 1.2' in good condition. Set reference points for construction.

7-11-2008 County Survey Crew removed CIM.

4-29-2010 County Survey Crew set a 4' telspar pipe w/cast iron cap down 0.1' from GPS coordinates.