Certificate of Location of Government Corner

ID#: 742005 **Description:** SEC COR 19 20 29 30 74 **Date Set:** 2/15/2002 **County:** Omsted

Section: 20 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 12' east of centerline of road, 10' south of fence west and 12' south of fence east and 23' North of centerline of Hathaway driveway East
County Survey Disk in PP #51011 E 13.77'
County Survey Disk in gate post NE 34.89'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, Karrick, Deputy Surveyor, North between sections 29 and 30. 80.00 chs. Set section corner post. Erected mound with trench, pits, charred stake and osage orange seeds at each angle.

8-1857 Thomas Hunter (P. 36 No. 58), County Surveyor, used corner.

5-1863 Compton (P. 70 No. 100) used corner.

10-1877 T. Hunter (P. 321 No. 315) measured line from S.W. Cor. 19 east but could find no evidence or knowledge of corner. Set no corner.

4-17-1975 County Surveyor reset this corner by lost methods (double proportionate measure). Measure East = 2651.68', Measure West = 2651.68', Measure North = 2633.51', Measure South = 2633.51'.

2-14-1984 County Surveyor found CIM down 1'.

2-14-2002 County Surveyor found CIM down 1.4' in good condition.

2-15-2002 County Surveyor set 1" square pipe w/cap over CIM at surface.