Location of Center of Section

ID#: 742009 **Description:** SEC CEN 20 74 **Date Set:** 11/3/2015 **County:** Olmsted

Section: 20 **Township:** 107N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" copper plug with punch mark

Reference Ties:

The corner falls on east edge of catch basin north at intersection of CSAH 4 and Superior Dr. NW
This corner is located by GPS reference stations "Superior A & Berean"

Corner History:

7-18-1857 T. Hunter P.36, No.57 Run & sub-divided E-W1/4 line 20. east 19.66 (1297.56' west 20.04 (1322.64'. Meas. from 1/16 east-north 39.73 (2622.18' Meas. from 1/16 west-north 39.81 (2627.46'

6-1863 P.C. Compton, Pg. 75 No. 109 Set center sec. at intersecting lines. Subdivided N.E. 1/4 & S.E. 1/4 into 1/4, 1/4 sections.

6-15-1892 T. Fraser, P.489, No.464, Found stake set former surveyors, used to set E1/4 20 by itners of N-S section line and line from W1/4 20 over stake found at center 20, set new stake at center 20. Meas. center 20 east to established corner, within 2 lks. of P. 36 - County Highway Department B.89 P.75 found old stake, hub in fence S. 76.75 set 1/2" rod, 2x2 hub, hub in fence N. 69.45 Meas. west 2646.63, 6" oak NE 59.6, Sp D FP S. 41.39, 15" Oak N.W. 65.9 Sp. D corner F P NNE 32.58.

5-1956 County Highway Department Found stake. Hub in fence S. 76.75 set 1/2" rod, 2x2 hub. Hub in fence N 69.45 meas. west 2646.63. 6" Oak NE 59.6 Sp D FP S. 41.39. 15" Oak NW 65.9 Sp D corner fence post NNE 32.58.

2-1974 County Surveyor removed rod set by County Highway Department Dug and found wood stake below the rod. Reset a 3/4" pipe 0.17' S of County Highway Department rod. On the E-W 1/4 line.

6-1974 County Surveyor prior to road regrading: Center of 4" dia. steel corner fence post (fences N-S-E) south 91.90', County Surveyor disc in PP #21886 SW 142.13'.

4-16-1975 County Surveyor found 3/4" rod set by County Highway Department on south shoulder of road ties checked OK.

6-16-1998 Yaggy Colby found and used 3/4" iron.

7-26-2000 Yaggy Colby found and used 3/4" iron at center of section 20 for surveys and subdivision of Badger property.

3-6-2002 County Surveyor visited area of corner. Found nothing.

5-27-2004 Yaggy Colby found and used 3/4" iron.

5-9-2005 Yaggy Colby found and used 3/4" iron.

8-22-2007 County Surveyor set 1" square pipe w/cap at surface from GPS & traverse data.

11-3-2015 The previous survey monument was destroyed by CSAH 4 road construction. County survey crew set a 1" copper plug with punch mark at the surface from previously measured coordinates