Certificate of Location of Government Corner

ID#: 742405 **Description:** SEC COR 23 24 25 26 74 **Date Set:** 9/9/63 **County:** Olmsted

Section: 24 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

Disk in 8" Oak NNE 7.82'
Disk in 10" Oak SW 17.14'
Corner of house NNW 42.30'
Post w/sign 4' South
This corner is located by GPS reference stations "Pit Bull A & B"

Corner History:

1854 Gov't. Notes, Michael Karrick, Deputy Surveyor, North between sections 25 and 26. 80.00 chs. set post for corner to sections 23, 24, 25 & 26. Burr Oak 6" N33°W 63 lks. Burr Oak 10" N64°E 96 lks. Dug trench.

9-1858 Thomas Hunter, Co. Surveyor, (Book A, Pg. 56, No. 82) used this corner to set the 1/16th South (20.32 chs.).

5-1874 T. Hunter (Book A, P. 241, No. 242) found old original corner standing in fence and also the NW witness tree. The other witness tree was gone. Tested the stake by the field notes and found it O.K. Set the 1/16th West midway (19.92 chs.) and on line.

5&12-1874 T. Hunter (Book A, P. 246 No. 247) found the section corner standing in mound. Tested it by the NW bearing tree still standing. Found the stake set P. 241 at the 1/16th west. Set a stake midway (19.731/2 chs.) and on line at the 1/16th North.

6-1876 T. Hunter (Book A, Pg. 300 No. 295) found the original corner standing and the NW witness tree standing, the other cut and gone. Tested stake by field notes and found it correct. Set the 1/16th South midway (20.39 chs.) and on line and the 1/16th East midway (20.24 chs.) and on line to the N.1/4 Cor. 25 (reset this survey).

8-17-1876 T. Hunter (Book A, Pg. 303 No. 298) found original corner standing.

5-1931 John Kerr, Co. Surveyor, (Kerr Book 5 Pg. 43) states he "found the corner". He either found or set a 1/2"x29" iron pin. Measured west 26.14.4 to 1/4 Cor. 23-26.

1938 J. Kerr (Kerr Book 14, Pg. 11) shows an iron at the corner and a measure north of 2607.4 to a boulder at 1/4 cor. 23-24.

1940 J. Kerr (Kerr Book 22, Pg. 4) shows a 1" pipe at the corner. Measured south 2680.56 to the W. 1/4 Cor. 25 and set a 1" pipe at the 1/16th midway and on line. He shows a measure of 2667.15 east to a stone at the N. 1/4 Cor. 25.

1941 J. Kerr (Kerr Book 25, Pg. 58) shows 1" iron pipe at the corner.

1954 J. Kerr (Kerr Book 60, Pg. 25) shows a measure 2607.4 north to 1/4 Cor. 23-24.

1957 J. Kerr (Kerr Book 71, Pg. 11) shows a 1" pipe at the corner, a measure 2665.70 east to the N. 1/4 cor. 25 and 2677.80 south to the W. 1/4 Cor. 25.

1961 J. Kerr (Kerr Book 83, Pg. 35) shows an iron at the corner, a measure north of 2607.4 to a stone at 1/4 cor. 23-24 and east of 2665.70 to a limestone at 1/4 cor. 24-25 with a 11/4" pipe at the 1/16th East midway and on line.

9-1963 J.Kerr set CIM over 1" x 12" pipe. RPs-center 8" white oak S61°E 36.5, center 3" white oak S21°15'W 11.9, center 8" pin oak N46°E 17.6

3-14-1974 County Surveyor visited corner - white post 1' E of monument.

4-25-1979 County Surveyor shot CIM in survey for city engr.

1980 WHKS referenced corner.

12-15-2003 County Surveyor found CIM in good condition down 0.1'. Rechecked ties; disc in 8" oak NNE 7.82', disc in 10" oak SW 17.14', Elm destroyed. Set post w/sign 4.0' south.